

NIB ANNUAL REPORT 2018

Safety Investigation Authority

FINLAND



PREFACE TO THE REPORT

This is the annual report of railway sector of the Safety Investigation Authority, Finland for calendar year 2018.

National investigation ID

From the beginning of year 2012 the identifying of accident investigation reports has been changed.

The new identifier

Accident/incident categories

- L Aviation accidents and incidents
- R Rail accidents and incidents
- M Marine accidents and incidents
- Y Other accidents and incidents
- P Exceptional events

Investigation identifier

Each investigation is designated by an identifier that consists of three parts, such as R2012-01.

- The first part refers the accident category (L, R, M, Y or P).
- The second part refers to the year of the accident.
- The third part is a sequence number referring to the order of the accident within its accident category in the year in question. "S" in the beginning of the number means that the investigation is theme investigation.

The old identifier

Terms used in this report:

Investigation categories					
A-investigation	Major accident				
B-investigation	Accident or serious incident				
C-investigation	Incident, damage or minor accident				
D-investigation	Other incident				
S-investigation	Safety study				

Investigation identifier:

Each investigation is designated by an identifier that consists of four parts, such as A1/1998R.

The first part refers to the investigation category (A, B, C, D or S).

The second part is a sequence number referring to the order of the accident within its accident category in the year in question.

The third part refers to the year of the accident.

The fourth part indicates the accident category (L, R, M or Y).

E.g. A1/1998R refers to the first major railway accident investigation in 1998.



CONTENTS

PF	PREFACE TO THE REPO	ORT	I
1	INTRODUCTION TO T 1.1 Legal Basis 1.2 Role and Mission 1.3 Organisational flo	THE INVESTIGATION AUTHORITY	1 1 1
2	INVESTIGATION PRO	CESSES	3
	2.1 Cases to be invest	stigated	3
	2.2 Institutions involve	ed in investigations	3
3	INVESTIGATIONS		5
	3.1 Overview of invest	stigations completed in 2018, identifying key trends	5
	3.2 Investigations cor	npleted and commenced in 2018	5
	3.3 Safety Studies co	mpleted and commenced in 2018	6
	3.4 Summaries of inv	estigations completed in 2018	7
	3.5 Comment and intr	roduction or background to the investigations	14
	3.6 Accidents and inc	idents investigated during last five years (in 2014-20	018)15
	3.7 Preliminary invest	tigations	15
	3.8 Fatal level crossir	ng accidents investigated by the road accident invest	igation teams16
4	RECOMMENDATION	S	19
	4.1 Short review and	presentation of recommendations	19
	4.2 Recommendation	ns 2018	20

ANNEXES

Annex 1. Recommendations



1 INTRODUCTION TO THE INVESTIGATION AUTHORITY

1.1 Legal Basis

The Safety Investigation Authority, Finland was founded in 1996 in connection with the Ministry of Justice. The tasks of the Safety Investigation Authority are specified in the relevant act (525/2011), which also include overall directions on the methods of investigation to be implemented. In Finland the Safety Investigation Authority is a multimodal investigation authority, which investigates aviation, maritime, rail and other accidents and incidents. The Safety Investigation Act also provides for the procedure to be followed in the event of exceptional and very serious events that, while not accident, had threatened or seriously damaged basic function in society.

The current Safety Investigation Act is in harmony with to the Railway Safety Directive.

1.2 Role and Mission

The purpose of the safety investigation is to promote general safety and to prevent any new accidents from occurring.

The safety investigation is conducted by the Safety Investigation Authority (SIAF). The safety investigation examines the course of events related to the accident or incident, their causes and consequences, and the search and rescue actions as well as the actions taken by the authorities. The investigation specifically examines whether safety had adequately been taken into consideration in the activity leading up to the accident and in the planning, manufacture, construction and use of the equipment and structures that caused the accident or incident or at which the accident or incident was directed. The investigation also examines whether the management, supervision and inspection activity had been appropriately arranged and managed. If necessary, the investigation also examines possible defects in the provisions and orders regarding safety and the authorities. The goal of the investigation is to discover factors and background causes contributing to the accident or incident in addition to its immediate cause, which may be found in e.g. the organisation, the instructions or the working methods.

When making the decision on whether to start the safety investigation, the seriousness of the incident and the probability that it will recur is taken into account. An incident or hazard with only minor consequences should be investigated if it caused a danger to several people and it is judged that the investigation will generate information that is significant in improving general safety and preventing accidents. The Safety Investigation Authority does not normally investigate incidents that have been caused deliberately or occur as a result of an offence.

The end result of the safety investigation is an investigation report. At the end of the report, there are safety recommendations addressed to the appropriate authorities and other agencies. The safety recommendations summarise the views of the investigators on how similar accidents and incidents can be avoided in the future. The Safety Investigation Authority monitors that the recommendations are implemented. The purpose of the safety



investigation is to promote general safety, prevent further accidents and incidents, and prevent losses caused by the accidents.

Safety investigations are not conducted to allocate legal liability. Other authorities and agencies are responsible for that task.

The task of the Safety Investigation Authority

The Safety Investigation Act (525/2011) defines the task and the mandate of the Safety Investigation Authority. The Safety Investigation Act of Finland provides for the types of accidents and incidents investigated by the Safety Investigation Authority and how they are investigated.

The task of the Safety Investigation Authority is to investigate all major accidents and serious incidents regardless of their type, as well as aviation, rail traffic and maritime traffic accidents and incidents.

The Safety Investigation Authority

- Ensures the general organisation, planning, guidance, provision of information, and supervision of the safety investigation
- Trains persons suitable to be investigators
- Maintains the readiness to quickly initiate an investigation
- Attends to international cooperation connected with the safety investigation field
- Issues safety recommendations and monitors their implementation.

1.3 Organisational flow





2 INVESTIGATION PROCESSES

2.1 Cases to be investigated

Accidents and incidents to be investigated:

- Rail traffic accident, which due to deaths or injuries, the extent of damage incurred to the environment, property or assets, or nature of the accident can be regarded as particularly serious (major accident)
- Serious railway accident as specified in Article 3 of the Directive (EU) 2016/798 of the European Parliament and of the Council on railway safety
 - train collision (with another train, a shunting unit or an object or obstacle within the clearance gauge) or derailment, resulting in the death of at least one person or serious injuries to five or more persons, or extensive damage to the rolling stock, the infrastructure or the environment (in excess of EUR 2 million)
 - any other railway accident with similar consequences, which has an obvious impact on railway safety (safety regulation or safety management)
 - level crossing accident, resulting train derailment, or resulting in the death of at least one or serious injuries to five or more members of the train crew or passengers, or if the accident was result of failures within the railway system, or which due to deaths or injuries, the extent of damage incurred to the environment, property or assets, or nature of the accident can be regarded as particularly serious
 - accident to persons involving rolling stock in motion at a station or railway yard (personnel, passengers), or in connection with a track maintenance operation (personnel)
 - fire in rolling stock when running between the departure station and the destination (including when stopped at the departure station, the interim and destination stops), and re-marshalling operations
 - other type of accident
- and any similar accident in private or public rail traffic
 - metro accident
 - tramway accident.

A serious incident and another accident or incident may be investigated in accordance with the Safety Investigation Act. Also, a joint investigation of several similar accidents or incidents may be conducted in accordance with the Act.

2.2 Institutions involved in investigations

The Safety Investigation Authority, Finland can investigate all rail accidents. Those investigations are independent, and reports are public. According to the Railway Act the Finnish Transport Safety Agency can investigate those occurrences SIAF does not investigate. Investigation reports are not public.



Level crossing accidents

The road accident investigation teams investigate all fatal road and off-road traffic accidents in Finland, including level crossing accidents. Preventing them is crucial from the human perspective in particular, but also from the economic perspective. In addition, the teams investigate on project basis accidents that have caused serious personal injury and property damage to clarify certain specific questions.

The main aim of the investigation is to promote road safety. Accident investigations do not comment on guilt or compensation issues.

Investigation is regulated by legislation on the investigation of road and off-road traffic accidents (Act on the investigation of road and cross-country traffic accidents, 24/2001, since 1.1.2017 Act on the investigation of road and off-road traffic accidents, 1512/2016).

The Finnish Crash Data Institute (OTI) coordinates the work of road accident investigation teams but does not intervene in the independent working of the teams. OTI also takes care of the training of the teams, the use of investigation results, and information services.

There are 20 investigation teams operating in different parts of Finland. They have a total of approximately 300 members. The teams are mainly positioned according to the current regional borders. The teams independently study the reasons for road accidents and make proposals to improve safety. The investigation team members are subject to public liability and a non-disclosure obligation.

The task of the road accident investigation teams is to determine the underlying reasons for an accident and to propose the necessary actions to improve traffic safety. The material collected is used in traffic safety work, the work of public authorities, international cooperation and communication. The teams do not investigate guilt or compensation issues related to accidents.

In addition to that what has been told above about the investigation of road and off-road accidents, we would like to mention, that SIAF can investigate any accident which has taken place in Finland, including road and off-road accidents. When SIAF has initiated an investigation, another authority or instance that has initiated its safety investigation shall transfer to SIAF the investigation materials that it has compiled. SIAF has investigated about 80 level crossing accidents and made four safety studies on level crossing accidents.



3 INVESTIGATIONS

3.1 Overview of investigations completed in 2018, identifying key trends

Type of acci-	Number	Number	of victims	Damages in	Trends in rela-
dents investi- gated	of acci- dents	Deaths	Seriously Injured	€(approxi- mation)	tion to previous years
Collisions	1	0	0	110 500	
Derailments	0				
Level cross- ing accidents	1	4	3	270 000	
Other	1	0	0	25 000	

3.2 Investigations completed and commenced in 2018

Investigations completed in 2018

Date of occurrence	Title of the investigation (Occurrence type, location)	Legal basis	Completed (date)
28.6.2017	Runaway of a maintenance machine in Ylivieska, Finland, on 28 June 2017	I (2) (a)	14.2.2018
21.9.2017	Collision between shunting unit and wag- ons standing on the tracks at Kouvola on 21 September 2017	l (2) (a)	1.6.2018
26.10.2017	Level crossing accident which led to four deaths at Raasepori on 26 October 2017	l (1)	7.6.2018

Investigations commenced in 2018

Date of occurrence	Title of the investigation (Occurrence type, location)	Legal basis
7.4.2018	Derailment of tank wagons at Mäntyharju 7 April 2018	l (2) (a)
12.12.2018	Level crossing accident at Kuusivaarantie level crossing in Kemijärvi on 12 December 2018	l (1)

The Legal Basis for the decision to investigate accident/incident:

I National rules imposed by implementing of the Directive on railway safety

- (1) in light of Article 20, §1
- (2) in light of Article 20, §2
 - (a) the seriousness of the accident or incident
 - (b) it forms part of a series of accidents or incidents relevant to the system as a whole
 - (c) its impact on railway safety on a Community level
 - (d) requests from infrastructure managers, the safety authority or the Member State
- (3) in light of Article 22
 - (§5) cross-border investigation or request to assistance

(§6) other reasons than those referred to in Article 20

- II Other national rules/regulations (covering possible areas excluded in Article 2, §2 and §3)
 - (2) (a) metros
 - (2) (b) trams and other light rail systems
 - (2) (c) networks that are functionally separate from the rest of the railway system
 - (3) (a) privately owned railway infrastructure, including sidings, used by the owner or by an operator for the purpose of their respective freight activities or for the transport of persons for noncommercial purposes, and vehicles used exclusively on such infrastructure
 - (3) (b) infrastructure and vehicles reserved for strictly local, historical or tourist use
 - (3) (c) light rail infrastructure occasionally used by heavy rail vehicles under the operational conditions of the light rail system, where it is necessary for the purposes of connectivity of those vehicles only



- (3) (d) vehicles primarily used on light rail infrastructure but equipped with some heavy rail components necessary to enable transit to be effected on a confined and limited section of heavy rail infrastructure for connectivity purposes only
- III Other national rules/regulations not referred to the Safety Directive.

3.3 Safety Studies completed and commenced in 2018

Safety Studies completed in 2018

Date of commission	Title of the Study (Occurrence type, location)	Legal basis	Completed (date)

Safety Studies commenced in 2018

Date of commission	Title of the Study (Occurrence type, location)	Legal basis



3.4 Summaries of investigations completed in 2018



R2017-01

Runaway of a maintenance machine in Ylivieska, Finland, on 28 June 2017

At 7.07 in the morning of 28 June 2017, a self-powered track maintenance machine used for track tamping began moving of its own accord from the western double-track work site located to the south of Ylivieska. The machine trailed a turnout leading from the work site to a track section used by traffic and rolled north on a track used by traffic for a distance of one kilometre, coming to a halt on track 1 of the Ylivieska station. Only moments before, the track section had been used by a freight train heading south. Passenger trains were on their way to the Ylivieska station from both south and north. The trains were supposed to pass each other in Ylivieska.

In the evening of 27 June, the maintenance machine had been used for track tamping at the western double-track work site located to the south of the Ylivieska station. The crew of the machine stopped work after two o'clock in the night and moved the machine to the crossover between the eastern track used by traffic and the western double-track under construction, and left it standing there. The unusual location was chosen to make work easier. The driver, who acted as the crew chief, contacted the Kokkola–Ylivieska traffic control and reported that the machine had been left standing on the crossover and that it would not affect rail traffic.

The Ylivieska–lisalmi traffic controller, under whose control the Ylivieska station also was, saw the centralised traffic control system showing the tracks become occupied to the south of the Ylivieska station. Because there was not supposed to be traffic in that area, the traffic controller called the engine driver of a passenger train waiting at the Ylivieska station and asked whether the driver could see any traffic on the track. The engine driver saw a lightless maintenance machine slowly rolling down the southern hill and coming to a halt on track 1 of the station. At the request of the traffic controller, the engine driver approached the machine and noticed that the parking brake of the machine was disengaged. The engine driver engaged the parking brake and ensured that the machine will stay in place by placing stop blocks in front of the wheels of the machine.

While rolling, the maintenance machine had occupied the track section to the south of the Ylivieska station, due to which the signal located further to the south had changed to the *stop* state. Due to this, the passenger train approaching from the south had to stop at the signal.

During the incident, the point machine was damaged. The damage totalled EUR 25,000. The incident caused three passenger trains to be delayed, with the IC train en route from Oulu to Helsinki delayed the most, 2.5 hours.

The maintenance machine started rolling after its pneumatic brakes released, because the parking brake had not been engaged. Furthermore, stop blocks intended to secure the machine in place had not been used. There was no clear distribution of critical duties for the machine, and critical



operations – such as engaging the parking break – were not verified when leaving the machine standing. In addition, the linkage of the machine's brake system was worn and poorly adjusted. These deficiencies had not been detected during the traffic worthiness inspection and safety inspection conducted on the machine one month earlier.

The location chosen for the machine to be left standing in was in conflict with the traffic safety plan of the work site in question. The crew of the machine did not have the knowledge required to intervene in the matter, because their induction had not included a review of the traffic safety plan. The general instructions in the field do not pay attention to locations where rolling stock may be left standing or how it should be secured in place.

The contractor who owns the machine did not have its own safety management system for trackwork. The Finnish Transport Agency's safety management system for trackwork had been specified to apply on the work site. The contractor's operations had not been audited by the Finnish Transport Agency, although deficiencies had previously been detected in the operations of said contractor, for example during investigation R2013-02 of the Safety Investigation Authority. The monitoring of trackwork safety issues on a practical level was found to be insufficient.

The traffic control did not have access to an up-to-date track diagram of the place of incident. For this reason, the traffic controller did not realise they should have intervened in the machine left standing on the crossover. The lack of documentation also slowed down clearing up the incident, because the centralised traffic control had no knowledge of the turnouts added to the track section used by traffic. The turnouts added to the track section used by traffic had not been connected to the centralised traffic control system; only their straight-running rails had been connected to be a part of the monitored track section.

In order to avoid similar incidents in the future, the Safety Investigation Authority recommends that the Finnish Transport Safety Agency (Trafi) ensure the implementation of the following new recommendations:

- 1. Already at the competitive tendering phase for the project, the Finnish Transport Agency should require each main contractor participating in track projects to have its own safety management system that takes the special characteristics of the companies and work sites into consideration and include monitoring of the realisation of these systems as part of its auditing process.
- 2. The Finnish Transport Agency should add instructions to the safety instructions of track maintenance (TURO) and the rail traffic and shunting work safety rules (Jt) on the locations where rolling stock may be left standing and the required procedures to secure it in place.
- 3. The Finnish Transport Agency should update Part 6, Safety devices, of the Railway Engineering Guidelines (RATO) so that the section of a turnout that sees traffic installed on a track section used by traffic must always be connected to the track circuit of the railway safety system as its own element and connected to the centralised traffic control monitoring immediately when technically possible.
- 4. The Finnish Transport Safety Agency should specify in more detail the checks required during a traffic worthiness inspection as well as the qualification and independence criteria for the party conducting the inspection.



In addition, the Safety Investigation Authority reiterates the recommendation issued during investigation R2013-02:

The Finnish Transport Agency will increase the field monitoring of trackwork safety regulations by allocating appropriate resources for such work. [R2013-02/S346]



R2017-02

Collision between shunting unit and wagons standing on the tracks at Kouvola on 21 September 2017

A shunting unit consisting of diesel locomotives, four empty hopper wagons and two container wagons loaded with tank containers containing hydrogen peroxide, on a container car collided with timber wagons standing in the eastern up yard at Kouvola at 9.47 pm on 21 September 2017.

The timber train had arrived in Kouvola on 19 September and was supposed to continue its journey to Kuusankoski on the same day. However, the final leg of the journey was cancelled. The intention was to move the wagons to their destination station on the afternoon of 21 September, but the train was cancelled, and the wagons were left to await a further transfer to track 843 of the railway yard on the night between 21 and 22 September.

Two shunting foremen were working in the shunting unit, taking turns to drive the locomotive by remote control. The shunting order being used gave instructions for the six wagons to be taken from Soramäki to the vacant track 843 at its eastern end. From Soramäki, route for the shunting unit was made to shunting signal 0823 in the direction of track 225.

The transfer to track 843 was accomplished as a pushing movement. The shunting foreman in the locomotive drove the locomotive by radio control and the shunting foreman on the wagon controlled the shunting movement via a radio telephone connection. After the signal had changed, the shunting foreman driving the locomotive used radio control to set a maximum speed request for the system of 35 km/h. As he saw the shunting unit turn towards the track with the standing timber wagon after the switch, the shunting foreman on the wagon shouted the signal *red* into the radio telephone. The shunting foreman driving the locomotive performed an emergency brake with the radio control. Despite the braking, the speed did not drop by much before the collision. The shunting foreman on the wagon struck a tank container on a container wagon, upon which the hydrogen peroxide in the tank container poured out. The collision caused a short circuit, which cut the power from the overhead contact wire in the Kouvola entry railway yard.



An emergency call about the accident was recorded at 9.50.32 pm. The caller stated that the location was the entry railway yard and that the rescue department would know the place. No actual street address was given. The emergency duty officer created an assignment code for *an accident of medium severity involving dangerous goods* at the Kouvola railway station. Rescue Department units moved into the vicinity of the railway station. The on-call fire chief requested a precise address from the traffic controller, but the traffic controller was unaware of the accident at that point. The units moved towards the scene of the accident on the basis of the address details. The on-call fire chief requested the disruption of traffic and power in the railway yard and raised the assignment code to *high severity*. Units were added to the assignment and the on-call officer at the Kymenlaakso Rescue Department was alerted. A situation centre was established at the Kotka Fire Station.

Two sectors were formed at the accident site. The first sector was for chemical diving, leak management and fluid pumping. The second was for isolating the accident area, investigating the nearby area, monitoring the spread of the vapour cloud and cooperating with the police. The rescue department contacted a company which manufactures hydrogen peroxide, which provided suitable pumping gear. The hydrogen peroxide left in the tank was pumped into containers brought from the company.

The shunting foreman on wagon in the shunting unit during the accident was injured. The first hopper wagon viewed from the locomotive was the worst damaged in the accident. The last hopper wagon of the shunting unit, the second container wagon and the tank containers on the second container car were damaged. In addition to the wagons on the shunting unit, the first wagon of the timber wagons was damaged. Of the track equipment, one sleeper and an overhead contact wire were damaged. As a result of the accident, around 11,000 litres of 40.1% hydrogen peroxide solution poured into the ground. The accident caused EUR 110,500 in costs. To determine the environmental impact of the accident, a groundwater pipeline was commissioned by the South East Finland ELY Centre and installed on the northern side of the site of the accident. No deviations have so far been detected in the samples taken from the pipeline. The accident caused delays for the Allegro train from St. Petersburg to Helsinki and ten freight trains travelling in the Kouvola area.

The chain of events leading to the accident originated in the cancellation of the transfer of timber wagons on the afternoon of 21 September. The root cause of the accident was the failure to notify the change of destination track for the wagons in the shunting unit. Upon entering the railway yard, the crew of the shunting unit did not notice that the destination track was occupied. This was partly due to the difficulty in identifying the tracks in the dark railway yard. The shunting movement that ended in the collision was performed at too great a speed. When it was noticed that the destination track was occupied, nothing could be done to prevent the collision. The shunting foreman acting as an observer in the wagon did not have a radio control unit. With a radio control unit, he might have been able to perform emergency braking a little faster, but this would not have prevented the collision. If the shunting movement had been performed at the permissible speed of 20 km/h, this would have left more time for braking after the danger of collision had been detected. In such a case, both the collision speed and damage would have been reduced. In addition, braking would have been faster if the shunting foreman on the locomotive had performed emergency braking with the locomotive's emergency stop button rather than by radio control. The investigation revealed that, in the radio control system used in locomotives of this kind, there is a two-second delay in all commands. In addition, there is no separate emergency stop button on the radio control unit.



There was a major difference in the level of experience between the shunting foremen working on the shunting unit. They were working in the shunting unit as shunting foremen of the same level, but the shunting foreman with three months of experience would have needed the guidance of a more experienced colleague and advice on the correct and safe way to perform shunting work.

It was observed that rolling stock training for shunting foremen at the training institution was too focused on rolling stock for passenger transport. In addition, there is currently no way of engaging in supervised practice in using radio control and communication devices at the training institution. For this reason, the correct procedures may remain unclear. This can be seen, for example, in the use of incorrect communication tools in shunting work.

Work guidance forms a major part of the training of shunting foremen. This is mainly done as part of normal work in the railway yard. A single trainee can have several work guidance instructors; in this case, they had nine. Work guidance may be insufficient due to lack of time, and there is no guarantee that all of the issues are covered when there are several occupational instructors. It was observed that the verification of skills at the end of the training, i.e. the documentation of the skills demonstration, was restricted to pass/fail, which gives no indication of the employee's ability to work independently.

There are no written instructions on performing and reporting track changes. Furthermore, there is no verification that such procedures have been completed. Lack of an operational model and assignment of responsibility pose a serious safety risk in railway yards. Because a number of shunting operators work in the yards, they must have consistent practices.

Radio-controlled locomotives are involved in collisions and *near-miss* situations, some of which are not reported to superiors. This is due to the sanction procedure used by the investigated railway operator. The investigation revealed that there may be large differences between the practices described in the safety management system and those used in practice. Official supervision is insufficient to ascertain whether an enterprise is operating in the manner described in the safety management system.

The initiation of rescue operations was slowed by problems in locating the site of the accident. No addresses had been entered for the yard in the emergency centre system. The railway yard employees had not been instructed on the use of emergency service routes when making an emergency call. Even the Emergency Response Centre was unaware of the emergency service routes and had no instructions to ask the caller about them.

In order to avoid similar accidents in the future, the Safety Investigation Authority recommends that the Finnish Transport Safety Agency (Trafi) ensure the implementation of the following recommendations:

- 1. When approving safety management systems and persons who are responsible for the verification of personnel skills, the Finnish Transport Safety Agency ensures that their skills verification methods are sufficient, and that skills verification is reported accordingly. Finnish Transport Safety Agency should provide instructions to training institutions in the railway sector on the creation of evaluation reports and monitor their use.
- 2. Training institutions in the railway sector include simulator training in the training programme for shunting foremen.



- 3. The Finnish Transport Agency draw up written instructions for track changes in railway yards and ensure that the operators in the yards act according to the instructions.
- 4. The Finnish Transport Safety Agency require that the radio control units used for shunting work have a separate non-delayed emergency stop button.
- 5. The Finnish Transport Safety Agency begin monitoring the practical implementation of safety management systems.

The Safety Investigation Authority also recommends the following:

6. The Emergency Response Centre add numbered emergency service routes for railway yards to its system, and emergency duty officers be instructed to locate the accident site primarily through such routes.

Additionally, the Safety Investigation Authority will open a recommendation in the investigation report C10/2003R, which is intended for the Finnish Transport Agency and is currently in the "Not to be implemented" status:

Railway yard tracks should be equipped with number plates.



R2017-03

Level crossing accident which led to four deaths at Raasepori on 26 October 2017

A rail bus travelling from Karjaa to Hanko collided with a Defence Forces high mobility terrain vehicle in Skogby, Raasepori, at an unprotected level crossing at 8am on Thursday 26 October 2017. A pioneer unit from the Uusimaa Brigade was engaged in an attack exercise, moving vehicles from Skogby to Syndalen in Hanko. There were eight conscripts in the high mobility terrain vehicle: three in the cabin and five on the platform. In addition to the driver, 15 passengers were travelling on the rail bus.

The conscripts in the cabin of the high mobility terrain vehicle did not notice the approaching train and did not hear its warning sound. There was insufficient time to reduce the speed of the rail bus, despite emergency braking by the train driver. The collision was serious. The conscripts travelling on the high mobility terrain vehicle were thrown out of the vehicle. Three conscripts and one rail bus passenger were killed in the accident. Three conscripts were seriously injured and two were slightly injured. Some rail bus passengers suffered minor injuries. The Defence Forces high mobility terrain vehicle were the accident and the nose section of the rail bus was damaged. The total costs caused by the accident were around €270,000.



Skogby's level crossing was particularly dangerous due to the angle of the track and road and the lack of warning devices. From the cabin in the high mobility terrain vehicle, it was difficult to see the train approaching at an angle from the rear. The section of line had a speed limit of 120km/h. A lower train speed would give train and vehicle drivers more time to react and take action as they approach a level crossing and would reduce the damage in possible collisions.

Level crossing improvements coordinated by the Finnish Transport Agency tend to have been made in order to increase the speed of railway lines. Because funds have been granted for the improvement of level crossings in conjunction with railway line projects, repairs have often not been targeted at the most dangerous level crossings. The Finnish Transport Safety Agency is aware of the problem but has not developed a better mechanism for improving the safety of level crossings.

Because the use of level crossings during the attack exercise had not been identified as a risk in the Uusimaa Brigade's risk assessment for the exercise and the level crossings to be crossed had not been named, the conscripts could not be warned about them. The risk assessment form used did not direct users towards the precise identification and naming of risks in the exercise taking place at the scene. Level crossing safety has not been a criterion affecting the choice of routes in the Uusimaa Brigade, or elsewhere in the Defence Forces.

Seatbelts were not in use in the high mobility terrain vehicle. The use of seatbelts would have reduced the severity of the injuries suffered by the conscripts and may even have saved lives. Seatbelts in the cargo space seating module are difficult to use when in combat gear. Seatbelts are often not used when travelling in a high mobility terrain vehicle.

Sufficient help was not initially available for all of the seriously injured people at the scene of the accident. There was a 4–5 minutes delay in the arrival of emergency care, due to the route driven. The emergency response centre did not guide the vehicles in their choice of route. At first, the emergency duty officer did not succeed in creating an accurate situational awareness of the accident. An operational area command (OAC) was not established close to the scene of the accident by the authorities. An OAC would have facilitated the coordination and communications of emergency care and rescue operations. Some of the next of kin and relatives of the victims of the accident found it difficult to obtain information on the status and location of the victims. There were problems in making official notifications of deaths. Many of the victims, their next of kin and relatives were assisted by crisis support efforts.

To avoid similar accidents and improve safety, the Accident Investigation Board recommends that:

- 1. The Defence Forces develop the risk assessment of exercises in order to identify the actual risks and name those which are identified.
- 2. The Finnish Transport Agency and the Finnish Transport Safety Agency ensure that resources are allocated to improving the safety of, or removing, the most dangerous level crossings.
- 3. The Finnish Defence Forces develop seatbelts in the cargo space seating module so that they are easier to use and enhance their monitoring of the use of seat belts.
- 4. The Ministry of the Interior ensure that an operational area command (OAC) is set up by the public authorities in the case of long-term or exceptional multi-authority tasks.



3.5 Comment and introduction or background to the investigations

Investigations commenced in 2018 and not followed

Date of oc- currence	Title of the investigation (Occurrence type, loca- tion)	Legal basis	Reason of non- following or suspension of investigations	Who, why, when (de- cision)



3.6 Accidents and incidents investigated during last five years (in 2014–2018)

Rail investigations in 2014–2018

Accidents investigated			2015	2016	2017	2018	TOT
	Train collision	0	0	0	0	0	0
lents	Train collision with an obsta-	0	0	1	0	1	2
cid .1)	Train derailment	0	0	0	0	0	0
ac : 20	Level crossing accident	0	0	1	1	1	3
erious (Art	Accident to person caused by RS in motion	0	0	0	0	0	0
Se	Fire in rolling stock	0	0	0	0	0	0
	Involving dangerous goods ¹	0	0	0	0	1	1
	Train collision	0	0	1	0	0	1
ts 22.6)	Train collision with an obsta-	0	0	1	1	0	2
den vrt 2	Train derailment	0	0	2	0	0	2
cic - (A	Level crossing accident	0	1	0	0	0	1
Other ac t 20.2) +	Accident to person caused by RS in motion	0	0	1	0	0	1
	Fire in rolling stock	0	0	0	0	0	0
(Ar	Involving dangerous goods ¹	0	0	1	1	0	2
	Incidents	0	15 ²	0	1	0	16
	TOTAL	0	16	7	3	2	28

3.7 Preliminary investigations

The Safety Investigation Authority has made, in compliance with section 8 of the Safety Investigation Act (525/2011), preliminary investigations. The SIAF has decided on the basis of a preliminary investigation, that the special characteristics of the case do not require the starting of the full investigation, but the report on the preliminary investigation is sufficient from the point of view of the safety advantage to be obtained. In the report is described briefly the events which have led to the accident and the immediate and indirect causes, which have been found in the preliminary investigation. In the reports there are not issued recommendations, but observations and suggestions for the measures to the actors. The reports are published only in Finnish.

In 2013 we started to publish reports of preliminary investigations in SIAF internet pages. In 2017 we developed a new layout of the report.

During the year 2018 SIAF didn't publish any preliminary investigation reports of rail occurrences.

¹ Belongs also to another category and is not calculated another time to the total amount.

² Cases belongs to the theme investigation on wrong routings in train traffic in 2015.



3.8 Fatal level crossing accidents investigated by the road accident investigation teams

In 2018 occurred a total of 27 level crossing accidents, four of them were fatal. Four persons injured fatally in the accidents, two injured seriously and one injured slightly. The road accident investigation teams investigated the fatal level crossing accidents happened to a vehicle³. Below short summaries of the accidents happened to vehicles.

1. Fatal level crossing accident in Heinävesi on 1 May 2018

On Tuesday, 1 May 2018, a level crossing accident involving a private car and a passenger train (railbus) occurred on the Nurkkalantie level crossing in Heinävesi. Speed of the train was 110 km/h and speed of the car was slow. The level crossing was passive. The accident was fatal to the car driver and the passenger of the car injured seriously. The car was wrecked beyond repair. The train sustained minor damages in front and side of the railbus.

The direct cause (*the key event*⁴) of the accident was that the car driver drove onto the level crossing without stopping.

The car driver failed to notice the train approaching from the left. (*immediate risk factors*⁴).

Background risk factors4:

- the level crossing was familiar to the car driver, which possibly reduced the attentiveness
- rain and the possible frosting of glasses weakened the visibility from the side windows
 of the car
- the crossing angle between the track and the private road forced the driver to watch backward to the left to see the train arriving.

In order to prevent similar accidents, the investigation team made the following improvement *proposals and safety recommendations*:

- the level crossing should be equipped with half-barrier installation
- fronts of locomotives should be equipped with systems which improve crash safety
- the crossing angle should be made correct way
- the speed of the trains should be lowered at unprotected level crossings.

2. Fatal level crossing accident in Turku on 7 May 2018

On Monday, 7 May 2018, a level crossing accident involving a private car and a passenger train occurred on the Vaalantie level crossing in Turku. Speed of the train was 140 km/h and speed of the car was about 40 km/h. The level crossing was active, automatic with user side protection. The accident was fatal to the car driver. The car was wrecked beyond repair. The train sustained minor damages in front of the locomotive. The level crossing barrier broke.

³ SIAF has investigated the Kuusivaarantie level crossing accident. The road accident investigation team started to investigate also that case, but according to our legislation stopped the investigation and gave all information they got to SIAF.

⁴ Terms used by the road accident investigation teams.



The direct cause (*the key event*⁵) of the accident was that the car driver drove through barrier onto the level crossing.

The car driver failed to notice that the barrier was in lower position or drove purposely through the barrier. (*immediate risk factors*⁴).

Background risk factors4:

- the car driver may have concentrated on other than following the traffic and didn't that's why notice the barrier being in lower position
- the level crossing was familiar to the car driver
- it is possible that the mood of the car driver and haste caused the driver defiantly and thoughtlessly drive through the barrier; in that case the driver did not probably see the train
- the driver was in a hurry and the driver had not reserved enough time
- the level crossing is located on an extremely lively section of line at the junction of several residential areas; there are about 5 000 vehicles per day moving at the level crossing, buses also and plenty of light traffic
- there is a considerable speed difference between a train and other traffic; it is difficult to estimate the approaching speed of the train especially when it is coming toward.

In order to prevent similar accidents, the investigation team made the following improvement *proposals and safety recommendations*:

- entrance of a vehicle to the track should be prevented with whole barriers when a train is approaching
- wider safety area before level crossing and monitoring system joined to it and alarm system which will warn the engine driver when inside the safety area there are persons or vehicles
- replacement of the level crossing with a graded interchange
- emergency braking assistant of vehicles which slows down automatically when perceiving an obstacle
- visible camera surveillance as preventive measure of traffic offences
- improving sightlines by means of trimming trees and bushes
- informing and education of preparing for the possible time-consuming drags of the way to work and of scheduling of the journey to work
- informing and enlightening to be continued to the road users about the risks which are related to the level crossings and to the crossing of them
- fronts of trains should be equipped with systems which improve crash safety, for example air bellows.

3. Fatal level crossing accident in Tervola on 23 August 2018

On Thursday, 23 August 2018, a level crossing accident involving a private car and a passenger train occurred on the Hallaojantie level crossing in Tervola. Speed of the train was 126 km/h and speed of the car was slow. The level crossing was passive, equipped

⁵ Terms used by the road accident investigation teams.



with STOP signs. The accident was fatal to the car driver. The car was wrecked beyond repair. The train sustained minor damages in front and side of the locomotive.

The direct cause (*the key event*⁶) of the accident was that the car driver drove onto the level crossing when the train was approaching from the left.

The car driver did not follow a sufficient carefulness when approaching the level crossing. (*immediate risk factors*⁴).

Background risk factors⁴:

- the level crossing was too familiar to the car driver
- the driver's attention had been possibly fixed on the hay bales which had just recently appeared on the field
- the driver's high age may have affected to the ability to make observations and decisions in the traffic situation
- the driver had serious illnesses
- the level crossing was unprotected
- difference in weight and size of the vehicles.

In order to prevent similar accidents, the investigation team made the following improvement *proposals and safety recommendations*:

- adding of the protected level crossings (equipped with barriers)
- before crossing of an unprotected level crossing, one should always stop to secure safe crossing
- the unprotected level crossings should be equipped with STOP signs
- the follow-up of the old drivers' driving health has to be developed
- it would be good to have a dashcam on both the cars and the trains, for example to clarify the accident event
- the level crossing should be removed, and the road traffic directed to the nearest (4 kilometres to south) level crossing equipped with warning devices.

⁶ Terms used by the road accident investigation teams.





4 **RECOMMENDATIONS**

4.1 Short review and presentation of recommendations

Implementation of recommendations during 2007–2018

Recommendations issued		Recommendation implementation status						
		Imple	mented	In pro	In progress		Not to be imple-	
						me	ntea	
Year	[No.]	[No.]	[%]	[No.]	[%]	[No.]	[%]	
2007	25	14	56,0	0	0,0	11	44,0	
2008	21	11	52,4	3	14,3	7	33,3	
2009	17	15	88,2	0	0,0	2	11,8	
2010	15	14	93,3	0	0,0	1	6,7	
2011	18	18	100,0	0	0,0	0	0,0	
2012	24	18	75,5	4	16,7	2	8,3	
2013	10	10	100,0	0	0,0	0	0,0	
2014	10	7	70,0	3	30,0	0	0,0	
2015	12	8	66,7	4	33,3	0	0,0	
2016	7	5	71,4	2	28,6	0	0,0	
2017	14	7	50,0	7	50,0	0	0,0	
2018	14	2	14,3	12	85,7	0	0	
TOTAL	187	129	69,0	35	18,7	23	12,3	

Implementation status of recommendations, see Annex 1.

A total of 391 recommendations were issued from the beginning of 1997 until the end of 2018. According to information available at 25 March 2019, 289 (73.9 %) recommendations were implemented and 66 (16.9 %) were decided not to be implemented. Since beginning of 2007 until the end of 2018 a total of 187 have been issued. 129 (69.0 %) have been implemented, 23 (12.3 %) have been decided not to be implemented and 35 (18.7 %) are under implementation.





4.2 Recommendations 2018

S1 Contractor-specific safety management systems in trackwork

The Finnish Transport Agency did not require the contractors participating in the track project to have their own safety management systems; instead, it required the application of the Finnish Transport Agency's safety management system. The adoption of the system on a work site with several contractors and subcontractors was deficient, as was the monitoring of the adoption process. For these reasons, the Safety Investigation Authority recommends that:

Already at the competitive tendering phase for the project, the Finnish Transport Agency should require each main contractor participating in track projects to have its own safe-ty management system that takes the special characteristics of the companies and work sites into consideration and include monitoring of the realisation of these systems as part of its auditing process. [2018-S1]

The main contractor's safety management system must take the safety objectives set by the Finnish Transport Agency into consideration also with respect to subcontractors.

S2 Instructions on the locations where rolling stock may be left standing and ensuring that it remains in place

The instructions currently in use do not pay attention to the standing locations and the related procedures for rolling stock. In this respect, the missing instructions give the operators free hands in where and how to leave rolling stock standing, which may at worst lead to a serious accident. The instructions are particularly important in the case of maintenance machines, as their movements and locations are not known by the centralised traffic control. For these reasons, the Safety Investigation Authority recommends that:



The Finnish Transport Agency should add instructions to the safety instructions of track maintenance (TURO) and the rail traffic and shunting work safety rules (Jt) on the locations where rolling stock may be left standing and the required procedures to secure it in place. [2018-S2]

The procedures for ensuring that rolling stock remains in place must specify in which situations the use of stop blocks and in which situations the use of lockable blocks is required in addition to the parking brake.

S3 Connection of turnouts installed on a track section used by traffic to the monitoring of the centralised traffic control

In the worst case, the inability of the centralised traffic control to see turnouts installed in a track section used by traffic and their incomplete connection to the railway safety system could have caused a serious accident if the maintenance machine had stopped in the turnout section. Furthermore, the inability of the centralised traffic control to see the turnouts caused a significant slow-down to the post-incident track inspection operations. For these reasons, the Safety Investigation Authority recommends that:

The Finnish Transport Agency should update Part 6, Safety devices, of the Railway Engineering Guidelines (RATO) so that the section of a turnout that sees traffic installed on a track section used by traffic must always be connected to the track circuit of the railway safety system as its own element and connected to the centralised traffic control monitoring immediately when technically possible. I2018-S31

A turnout on a track used by traffic should always be visible in the centralised traffic control system so that the traffic controller is able to locate the turnout. The visibility of the turnout to the centralised traffic control also improves trackwork safety, as the turnouts and their numbers are carefully specified in the trackwork notifications.

S4 Development of the commissioning permit procedure for individual machines of the type in use

At the time the incident occurred, the brake system of the maintenance machine was worn and poorly adjusted. This was the case despite a Finnish Transport Safety Agency (Trafi) traffic worthiness and safety inspection that had been conducted on the machine before it was taken into use. At the request of Trafi, extensive tests and measurements were performed on the machine, analysing the characteristics of the machine type, despite the fact that the machine type has been used in Finland for over 20 years. The purpose of these tests remains unclear, as the visibly poor condition of the individual machine was not detected. One factor could have been the missing of the machine's maintenance documentation. The role of the party that conducted these inspections was unclear in the investigated incident, as the company also participated in the refurbishment of the machine. For these reasons, the Safety Investigation Authority recommends that:



The Finnish Transport Safety Agency should specify in more detail the checks required during a traffic worthiness inspection as well as the qualification and independence criteria for the party conducting the inspection. [2018-S4]

In addition to the general safety regulations, the traffic worthiness inspection must be based on the requirements specified by the machine manufacturer; for this reason, the first step of the inspection should always be a check of the maintenance documentation. Based on this documentation, it can be checked whether the condition of the machine meets the requirements for safe use specified by its manufacturer. For example, the monitoring of the regular maintenance of safety-critical brake components is impossible without up-to-date documentation.

S5 On-site trackwork monitoring

Instructions issued by the Finnish Transport Agency define the parties' responsibilities and tasks related to the safety of railway operations, such as trackwork. The instructions emphasise monitoring that has been defined to be primarily carried out in the form of written forms and reports. Work site monitoring is rarely performed on-site with the exception of separate inspection visits. Indeed, the on-site monitoring of compliance with trackwork safety regulations should be increased. An increased risk of getting caught for breaches of regulations efficiently directs the behaviour of both organisations and individuals. Along with this measure, actions that comply with safety regulations should be made financially attractive. For these reasons, the Safety Investigation Authority reiterates the recommendation issued in investigation report R2013-02:

The Finnish Transport Agency will increase the field monitoring of trackwork safety regulations by allocating appropriate resources for such work. [R2013-02/S346]

S6 Development of work guidance monitoring

Work guidance forms a major part of the training of shunting foremen. Trainee competencies are not sufficiently ensured, because the monitoring of work guidance does not give a true picture of the competencies of trainees. Nor does this ensure that all issues have been learned.

The Safety Investigation Authority recommends that

When approving safety management systems and persons who are responsible for the verification of personnel skills, the Finnish Transport Safety Agency makes sure that their skills verification methods are sufficient, and skills verification is reported accordingly. [2018-S14]

The work guidance instructor must document the competencies of the trainee after each shift. Likewise, the trainee must evaluate the outcome of his or her training. The employer must arrange sufficient time for the instructor and trainee to perform evaluations directly after each shift.



S7 Development of teaching tools

Training at the educational institute does not include the possibility to practice the use of radio-controlled equipment. Guided training on a simulator would improve the prepared-ness of trainees for work.

The Safety Investigation Authority of Finland recommends that

Training institutions in the railway sector include simulator training in the training programme for shunting foremen. [2018-S15]

The simulator should allow the use of different types of radio controllers. Practice with different types of communication equipment should be possible.

S8 Instruction on track changes in railway yards

Track changes are a daily activity in railway yards. If they are not done correctly and information is not passed onto the relevant parties, there is a high risk of accidents.

The Safety Investigation Authority recommends that

The Finnish Transport Agency draw up written instructions for track changes in railway yards and ensure that the operators in the yards act according to the instructions. [2018-S16]

In addition to the correct working practices, the instructions should include the correct responsible persons and confirm that critical procedures have been performed.

S9 Emergency braking by radio control

The radio control system of the locomotives responds slowly to the driver's commands. There is no separate *emergency stop* button on the radio control unit. The delay in the radio control system slows the start of emergency braking in critical situations.

The Safety Investigation Authority recommends that

The Finnish Transport Safety Agency (Trafi) require that the radio control units used for shunting work have a separate, non-delayed emergency stop button. [2018-S17]

As a direct measure, instructions should be given to initiate emergency braking by using the *emergency stop* button on the locomotive.

S10 Monitoring of the practical implementation of safety management systems

Near misses and minor collisions, which are not revealed, occur in the case of radiocontrolled locomotives. Users do not dare to report such incidents, due to fear of sanctions. There is no way of learning from *near misses* and collisions involving radio-controlled locomotives, which hampers the development of the safety of radio-controlled work. In the railway sector, safety management systems remain at the level of target setting,



since their implementation is virtually unsupervised by public authorities and there is little self-supervision.

For these reasons, the Safety Investigation Authority recommends that:

The Finnish Transport Safety Agency begin monitoring the practical implementation of safety management systems. [2018-S18]

Supervision should mainly be performed by interviewing randomly selected employees engaged in practical work, and comparing the information received from them with the content of the company's safety management system.

S11 Use of emergency service routes during emergency calls

Emergency service routes are marked in the rescue plans for railway yards for the transport of dangerous goods), along which routes into the area are planned in case accidents occur. However, these routes are largely unknown to the Emergency Response Centre Administration, and this could hamper and delay access to the accident site. For these reasons, the Safety Investigation Authority recommends that:

The Emergency Response Centre add numbered emergency service routes for railway yards to its system, and emergency duty officers be instructed to locate the accident site primarily through such routes. [2018-S19]

In order to be able to use emergency service routes in the event of an accident, it should be ensured that they are marked individually in railway yards and workers in the railway yards know where they are.

S12 Track numbering in railway yards

Several railway yards have not been equipped with clearly visible track numbers at the ends of tracks. Identifying the destination track can be difficult and it may come as a surprise that the track is occupied.

For these reasons, the Safety Investigation Authority will open Recommendation C10/2003R, intended for the Finnish Transport Agency in the investigation report, with the status "Not to be implemented":

Railway yard tracks should be equipped with number plates. [C10/2003R/S194]

Track numbers can be installed in the electrical track portal crossing the railway yard, for example.

S13 Development of risk assessment

The Defence Forces have developed their risk assessment with regard to exercises, but this work is still in progress. The current risk assessment form does not encourage naming identified risks, but these are evaluated by predetermined risk type (e.g. land or sea traffic accidents). If the risks involved in exercises are not identified and named, it is difficult to control and warn troops on exercise.



The Safety Investigation Authority recommends that

The Defence Forces develop the risk assessment of exercises in order to identify the actual risks and name those which are identified. [2018-S20]

For example, local risks associated with transport should be identified.

S14 Improving the safety of the most dangerous level crossings

Repairs of level crossings have not always focused on the most dangerous level crossings.

The Safety Investigation Authority recommends that

The Finnish Transport Agency and the Finnish Transport Safety Agency ensure that resources are allocated to improving the safety of, or removing, the most dangerous level crossings. [2018-S21]

When level crossings are removed, passage between several level crossings close to each other should be planned via a single safe connection.

S15 Improved usability of seatbelts and monitoring usage

Seatbelts in the cargo space seating modules of the Defence Force's high mobility terrain vehicles are difficult to use for soldiers in combat gear. The use of seatbelts is not effectively monitored. There are guidelines on the use of seatbelts and the monitoring of such use.

The Safety Investigation Authority recommends that

The Finnish Defence Forces develop seatbelts in cargo space seating modules so that they are easier to use and enhance their monitoring of the use of seatbelts. [2018-22]

S16 The establishment of an operational area command by the authorities should be routine

An operational area command (OAC) is not necessarily established close to the scene of an accident by the authorities, even in the case of major accidents. The threshold for establishing such a command should be lower.

The Safety Investigation Authority recommends that

The Ministry of the Interior ensure that an operational area command (OAC) is set up by the public authorities in the case of long-term or exceptional multi-authority tasks. [2018-23]

An OAC is the only effective arrangement for managing a situation involving multiple authorities/actors.

RECOMMENDATIONS

Date and time (Co	de):	17.1.2007, 10.52 (B1/2007R)					
Location:	*	Närp	ärpiö, Kallmossvägen / Karlå level crossing, unprotected				
Type of occurrenc	e:	Leve	_evel crossing accident, freight train – van				
Train type and nur	mber:	Freig	Freight train 3273, two Dv12 diesel locomotives and 35 wagons				
Road vehicle:		Van	/an Opel Astra, 2001 model				
			•	In the train	In the road vehicle		
Persons on board		Crev	V:	1	1		
		Pass	sengers:	0	0		
Fatally injured:		Crev	<i>v:</i>	0	1		
	Pass	sengers:	0	0			
Seriously injured:		Crev	v:	0	0		
		Pass	sengers:	0	0		
Slightly injured:		Crev	<i>v:</i>	0	0		
		Pass	sengers:	0	0		
Damages of rolling	g stock:	The	locomotive suf	fered minor damage while t	he van was wrecked		
	-	beyo	ond repair.	-			
Damages on track	equipment:	None	э.				
Other damages:		Deliv	verable post wa	as lost and damaged.			
Summary: On Wee	dnesday 17 Ja	nuary	2007 at 10.50	a.m. an accident occurred	d in Närpiö in which a		
train carrying lumbe	er on its way fr	om Š	einäjoki to Kas	kinen collided with a van a	t an unprotected level		
crossing.							
Final report issued: 23.11.2007							
Recommendation	Using the saf	ety be	elt in an accide	ent, even when driving at m	oderate speeds, may		
Nr. S227	prevent injury	or de	eath.				
	Compulsory	use	se of safety belts should be expanded to include delivery				
	vehicle drive	rs an	d passengers	, irrespective of the drivin	g distance.		
Date	Status		Comments				
20.1.2009	In progress		Finnish Trans	port and Logistics supports	pecause of safety rea-		
			sons.				
16.6.2011	In progress						
9.2.2012	In progress						
<u>19.9.2013</u>							
10.3.2014							
25.2.2015	Under implei	men-	The renewal of	of the road traffic legislation	is in progress.		
	tation						
3.3.2016	Under implei	men-	Waiting for the	e renewal of the road traffic	legislation.		
	tation						
28.3.2017	Under implei	mplemen- Waiting for the renewal of the road traffic legislation.					
	tation				<u></u>		
11.3.2018	Under implei	men-	Legislative pro	oposal will be presented to	Finnish parliament. It		
	tation		abes not inclu	ide mandatory use of safety	y beit in delivery vehi-		
40.0.0040	Not to be 1		CIES.	adation has wether a tot	ann an ta d in 10 an		
18.2.2019	Not to be in	pie-	The recomme	endation has not been impl	emented in 10 years.		
	mented		I ne active foll	ow-up has been discontinue	ea.		

Date and time (Code):	5.3.2007, 14.39 (B2/2007R)						
Location:	Nivala, Niskakanka	Nivala, Niskakankaantie / Pahaoja level crossing, unprotected					
Type of occurrence:	Level crossing accident, Passenger train – car						
Train type and number:	Local train H494, Dm12 rail bus						
Road vehicle:	Passenger car Renault Laguna Break 1.6, 2000 model						
	In the train In the road vehicle						
Persons on board:	Crew:	2	1				
	Passengers:	25	1				
Fatally injured:	Crew:	0	1				
	Passengers: 0 1						
Seriously injured:	Crew:	0	0				

Annex 1/2 (28)

		Passengers:	0	0		
Slightly injured:		Crew:	0	0		
		Passengers:	0	0		
Damages of rolling	g stock:	Slight damages to t	the rail bus, the car was cor	npletely wrecked.		
Damages on track	equipment:	None.				
Other damages:		None.				
Summary: On Mor	nday 5 March 2	2007 at 2.39 p.m.,	a level crossing accident t	ook place involving a		
passenger car and a	a rail bus travell	ing from Ylivieska to	o lisalmi. Both the driver and	the passenger of the		
car perished, while	the train persor	nnel and passenger	s were unharmed. The acc	ident wrecked the car		
beyond repair, while	e the train suffe	red only minor dam	age. The total material cos	ts due to the accident		
were approximately	EUR 70,000.	_				
Final report issued	1: 23.11.200	7				
Recommendation	The Pahaoja	unguarded level of	crossing is situated on a	busy private road in		
Nr. S228	Niskakangas v	which, in addition to	the locals, is used by regula	r taxi traffic and heavy		
	traffic due to f	arming and industr	y in the area. For train safe	ety alone, it would be		
	extremely imp	ortant that the level	crossing be equipped with	a warning station with		
	automatic gate	automatic gates. This measure would also increase the likelihood that a driver no-				
	tices an appro	aching train, thanks	to lowered or lowering gate	<u> S</u>		
	The Pahaoja	e Pahaoja unguarded level crossing should be equipped with a half barrier				
Data	equipment.	Commonto				
20.1.2000			ing to install the lovel cross	ing with barriore		
20.1.2009		Nivola town is	of the opinion that the low	al crossing should be		
10.0.2011	in progress	equipped with	half barriers.	er crossing should be		
9.2.2012	In progress					
19.9.2013						
10.3.2014						
25.2.2015	Under implen	nen- Financing for	the improvement of level of	crossing safety is not		
3 3 2016	Under implen	nen- No progress				
01012010	tation	ion no progrocor				
28.3.2017	Under implen	nen- No progress.				
	tation					
11.4.2018	Under implen	nen- Level crossing	g is number 52 at the TOP	100 list of most dan-		
	'tation	gerous level	crossings in Finland. New	track plan to be ap-		
		proved.	-	· · ·		
18.2.2019	Not to be im	ple- The recomme	endation has not been impl	emented in 10 years.		
	mented	The active foll	ow-up has been discontinu	ed.		

Date and time (Code):	6.5.2007, 15.33 (B4/2007R)			
Location:	Kiuruvesi, Pohja le	vel crossing, unprotected		
Type of occurrence:	Level crossing acci	dent, passenger train - car		
Train type and number:	Regional train 746,	two Dm12 rail busses		
Road vehicle:	Car Nissan Almera	4D Sedan, 2005 model		
		In the train	In the road vehicle	
Persons on board:	Crew:	2	1	
	Passengers:	≈60	1	
Fatally injured:	Crew:	0	1	
	Passengers:	0	0	
Seriously injured:	Crew:	0	0	
	Passengers:	0	1	
Slightly injured:	Crew:	0	0	
	Passengers:	0	0	
Damages of rolling stock:	The car was wrecked beyond repair. Equipment of the train's nose			
	and substructure were damaged			
Damages on track equipment:	The wooden covering on the level crossing sustained minor damage.			
Other damages:	None			

Annex 1/3 (28)

Summary: A fatal level crossing accident took place in Kiuruvesi, at the unprotected level crossing of Pohja. This accident occurred when a car travelling along the Pohja private road drove without stopping under a rail bus running from Ylivieska to lisalmi. There were two passengers in the car; the driver perished, and the front seat passenger was seriously injured.

Final report incurade 20.1.2009						
rinai report issue						
Recommendation	Since the Pohja lev	Since the Pohja level crossing is dangerous with regard to its conditions and very				
Nr. S234	near a safe overpa	ss, the investigation commission recommends:				
	The Pohja level c	rossing should be closed and a replacement overpass be				
	created at the Hila	apparannantie bridge.				
Date	Status	Comments				
20.1.2009	In progress					
19.2.2010	In progress					
18.8.2011	In progress					
9.2.2012	In progress					
19.9.2013						
10.3.2014						
25.2.2015	Under implemen- tation	Financing for the improvement of level crossing safety is not granted.				
3.3.2016	Under implemen- tation	No progress.				
28.3.2017	Under implemen- tation	No progress.				
11.4.2018	Under implemen- tation	There are no corrective actions planned for Pohja level cross- ing.				
25.3.2019	IMPLEMENTED	Pohja level crossing has been closed in December 2018.				

Date and time (Co	de):	9.3.2007, 16.13 (B	.3.2007, 16.13 (B3/2007R)		
Location:		Särkisalmi, Sinkonen level crossing, unprotected			
Type of occurrence:		Level crossing acci	dent, passenger train car		
Train type and nur	nber:	Regional train 746,	Dm12-railcar		
Road vehicle:		Car Mercedes Benz	z 190D, 1985 model		
			In the train	In the road vehicle	
Persons on board	:	Crew:	2	1	
		Passengers:	34	1	
Fatally injured:		Crew:	0	1	
		Passengers:	0	1	
Seriously injured:		Crew:	0	0	
		Passengers:	0	0	
Slightly injured:		Crew:	0	0	
		Passengers:	0	0	
Damages of rolling	g stock:	The railcar's blockage bumper and automatic coupling were dam-			
		aged, while the passenger car was severely damaged.			
Damages on track	equipment:	None			
Other damages:		None			
Summary: A level of	crossing accider	nt involving a passe	nger car and a rail bus trave	elling from Savonlinna	
to Parikkala took pl	ace in Särkisal	mi on 9 March 200	7 at 4.13 p.m. The driver	and passenger of the	
passenger car were	e killed but the	train personnel and	passengers escaped unin	jured. The passenger	
car was completely	wrecked, and t	ne train sustained n	ninor damage.		
Final report issue	d: 12.12.200	/			
Recommendation	Drivers cross a	a railway through t	he Särkisalmi level crossing	g, equipped with half-	
Nr. S237	barriers, as the	ey drive along Mel	konniementie to the Särkis	almi residential area.	
	This route is 2	00 metres longer th	han the route taken by the	vehicle driver through	
	the Sinkonen I	evel crossing. In or	der to prevent this dangerou	is shortcut from being	
	used, the Acci	ccident Investigation Board recommends:			
	The Sinkonen	en level crossing located in the Särkisalmi residential area should			
Dette	be removed.	/ed.			
	Status		it area of the treat has been	n la nath an c -l	
20.1.2009	In progress		in area of the track has bee	n lengtnenea.	
16.2.2010	in progress	Parikkala municipal executive board renews comment that the Sinko- nen level crossing should be equipped with warning installations.			

Annex 1/4 (28)

16.6.2011	Not yet imple-	The Parikkala municipality and Finnish Transport Agency do not
	mented	agree on the matter.
9.2.2012	Not yet imple-	
	mented	
19.9.2013	In progress	In municipal decission making process.
10.3.2014		
25.2.2015		
3.3.2016	Under implemen-	No progress.
	tation	
28.3.2017	Under implemen-	The opinion of the municipality is positive.
	tation	
11.4.2018	Under implemen-	Replacing road connections are studied, it is also possible that
	tation	level crossing will be equipped with half barriers.
18.2.2019	Not to be imple-	The recommendation has not been implemented in 10 years.
	mented	The active follow-up has been discontinued.

Date and time (Co	de):	13.8.2007, 15.15	3.2007, 15.15 (B5/2007R)			
Location: Nur		Nurmijärvi, Röykkä	rmijärvi, Röykkä, Leppälammentie / Korpi level crossing, unpro-			
		tected	xted			
Type of occurrence: Lev		Level crossing acc	evel crossing accident, Freight train – car			
Train type and nur	mber:	Freight train 3649,	2 Dv12 diesel locomotives	and 41 wagons		
Road vehicle:		Car Ford Sierra 2.0), 1990 model			
			In the train	In the road vehicle		
Persons on board	:	Crew:	1	1		
		Passengers:	0	1		
Fatally injured:		Crew:	0	0		
		Passengers:	0	1		
Seriously injured:		Crew:	0	1		
		Passengers:	0	0		
Slightly injured:		Crew:	0	0		
		Passengers:	0	0		
Damages of rolling	g stock:	Damages to the ec wrecked.	quipment of locomotive nose	e, private car entirely		
Damages on track	equipment:	None.				
Other damages:		None				
Summary: On Monday 13 August 2		st 2007 at 3.15 p.m	007 at 3.15 p.m., a level crossing accident occurred in Röykkä,			
Nurmijärvi, in which	a passenger	car collided with a	r collided with a freight train en route from Kirkniemi to Riihimäki,			
resulting in the deat	th of the car's p	bassenger and seric	enger and serious injuries to the car driver.			
Final report issued	d: 23.6.2008	}				
Recommendation	Because the	area's growing pop	pulation is continuously incr	easing the volume of		
Nr. S241	traffic at the	Korpi level crossing	g, and because fast growin	g bushes around the		
	crossing do n	ot enable the mainte	enance of visibility in line with	n Ministry of Transport		
	and Commun	ications and Finnish	n Railway Administration rec	quirements, the inves-		
	tigation comm	ission recommends	s the following:			
	The Korpi lev	el crossing shoul	d be equipped with half-ba	arriers.		
Date	Status	Comments				
20.1.2009	In progress	Will be equip	bed with half barriers, when	the financing is ok.		
19.2.2010	In progress	In action and e	In action and economic plan 2010–2013.			
18.8.2011	Not yet imple-	No funding ye	et.			
0.0.0040	Mented					
9.2.2012	Not yet imple-	•				
10.0.2012		No funding				
19.9.2013		No funding.	<u>, +</u>			
25.2.2014	Lindor implan		51.			
20.2.2010						
3 3 2016	Linder implo	men- No progress				
3.3.2010	tation					
28 3 2017	Linder imple	men- Municipality	has presented the beginning	a of the realization to		
20.0.2017	tation	ELY Centre.				

11.4.2018	Under tation	implemen-	Track plan will most likely be approved at the beginning of year 2019 and will be carried out during summer 2019.
25.3.2019	Under tation	implemen-	Level crossings in Hanko-Hyvinkää line will be reviewed as a part of electrification of line. For Korpi level crossing options are to move level crossing to different location or equip the level crossing with half barriers.

Date and time (Co	de):	21.11.2007 (B7/20)07R)		
Location:	uo):	Lahti. Heikinpellontie level crossing, unprotected			
Type of occurrenc	e:	Level crossing accident, freight train – car			
Train type and nur	mber:	Freight train 2873, Dv12 diesel locomotive			
Road vehicle:		Car Volkswagen G	olf 1.6, 1999 model		
			In the train	In the road vehicle	
Persons on board		Crew:	2	1	
	· •	Passengers;	0	0	
Fatally injured:		Crew:	0	1	
r dany mjaroar	ł	Passengers:	0	0	
Seriously injured:		Crew:	0	0	
	ł	Passengers:	0	0	
Slightly injured:		Crew:	0	0	
Oligitay injaisa.	ł	Passengers:	0	0	
Damages of rolling	a stock	The car was wreck	ed beyond repair. The front	of the locomotive	
Damages or romm	J Stoon.	eustained some da			
Damages on track	equipment:	Nono	inage.		
Other demander	equipment.	None			
Cliner damayes.	Natabar 2007 at	1255 nm a fatal k	wel crossing accident occur	red on an unprotected	
Summary. On Zr O	Clober 2007 at	12.00 p.m., a ratarie	Wel crossing accident occur	red on an unprotected	
level clossing along	Heikinpelionu	e foad in Lanu. The	accident occurred when a second secon		
road drove without :	stopping in nor	It of a locomotive en		I. The driver, who was	
the sole person in t	ne car, dieu in	Stantiy. The accider	At occurred because the un	Iver of the car du not	
see the train. The le	Vel crossing in	question meets reg	ulations concerning visionity	/ and crossing angles,	
but does not meet	those concern	ing wait platforms. It is possible that the driver was not sufficiently			
vigilant due to famili	arity with the c	ossing and the impression that train traffic was infrequent there.			
Final report issued	1: 9.9.2008				
Recommendation	Track renovation	tion investments ha	ave been scheduled for the	e Lahti-Heinola track	
Nr. S243	within the nex	t few years. The inte	ended focus is on track tech	nology renewal, but it	
	is clear that th	ie investments will a	lso cover raising level cross	sing safety to the level	
	set in technica	al track requirement	ts (RATO). Considering the	danger posed by the	
	level crossing	s along the track at	t the moment, it is recomm	ended that actions to	
	improve level	crossing safety are in	nitiated in advance before th	e investments proper.	
	Such actions	include the following	g: possible replacement of least statement statement of least statement statement of least statement sta statement statement stat statement statement state	evel crossings with al-	
	ternative road	J routing, sightline	improvements, wait platfor	m improvements and	
	crossing angle	adjustments.			
	Actions to im	prove level crossi	ng safety along the Lahti–	Heinola track should	
	be carried ou	t before the initiation of scheduled renovation investments.			
Date	Status	Comments			
20.1.2009	In progress				
19.2.2010	In progress	In some level	crossings there has been re	educed speed limit on	
		roads.			
18.8.2011	In progress	Lahti town pro	oposes to make a level cro	ssing plan and to en-	
10.0.2011	11 p. og. occ	close it to the	building program in the nex	t few vears.	
9 2 2012	In progress		building program in the		
10 0 2013	In progress I abti town has made a level crossing			an and has decided to	
19.9.2015	III piogress		st level crossing with barrier	ne nas decided to	
10 3 2014	ł		Stiever crossing with barrier	3.	
10.3.2014	Linder implor				
25.2.2015	Under implem	ien-			
0.0.0016	tation		the section will be installed	-l	
3.3.2016	Under impier	nen- Possibly allen	ITION DEVICES WILL DE INSTALLED	3.	
	tation	D all heatter		<u>.</u>	
28.3.2017	Under impier	nen-Possibly atten	ition devices will be installed	J.	
· · · · · · · · · · · · · · · · · · ·	i tation				

Annex 1/6 (28)

11.4.2018	Under	implemen-	Level crossing warning devices that are based on new technol-
	tation		ogy, will be installed during 2018.
25.3.2019	Under	implemen-	Procurement of warning devices for Lahti-Heinola line has been
	tation		delayed. Process is on-going at commercial court. 12 most dan- gerous level crossings will be equipped with half barriers during 2019.

Date and time (Co	de): 1	1.2.2009, 15.12 (B1/2009R)		
Location:	P	ori, Kyläsaari / Teurastamo level crossing, unprotected			
Type of occurrence:		Level crossing accident, freight train – car			
Train type and number:		Freight train 3864, diesel locomotive Dv12			
Road vehicle:	P	Private car Volvo S40, 1997 model			
			In the train	In the road vehicle	
Persons on board	C	rew:	1	1	
	P	assengers:	1	2	
Fatally injured:	C	rew:	0	0	
	P	assengers:	0	2	
Seriously injured:	C	rew:	0	1	
	P	assengers:	0	0	
Slightly injured:		rew:	0	0	
	P	assenders:	0	0	
Damages of rolling	n stock M	inor damages to	the locomotive. Car was ent	tirely wrecked	
Damages on track	equipment N	one			
Other damages	N	one			
Summarur A laval	crossing acciden	t took place at the	unprotected level crossing	of Toursetamo on the	
Mäntyluoto-Pori tra	ck and Pikakylän	tie road on Wedne	sday 11 February 2009 at	3 12 n m The engine	
driver emergency h	raked 20 metres	hefore the collision	on when the car had disan	heared from his sight	
The locomotive hit t	he middle of the	par's right side no	t being able to reduce spee	ad before the collision	
The car clung to the	front of the locor	notive and travelle	ed in front of it for 223 metre	s until the locomotive	
stopped Two passe	enders in the car	suffered fatal hea	d injuries in the accident ar	nd the driver was seri-	
ously injured The lo	comotive suffere	d minor damage	while the car was wrecked	beyond repair	
The accident was o	aused by the ca	r driver noticina	the train too late and not h	aving time to stop or	
otherwise prevent th	ne accident	anver nedering			
Final report issued	10 3 2010				
Recommendation	Time was waste	d in locating pro	blems between the engine	driver and the traffic	
Nr. S277	controller and be	etween the traffic	controller and the Emerger	cy Response Centre	
	Because of thes	e difficulties, the t	raffic controller had problem	s clarifying to the ERC	
	operator the loc	ation of the level of	crossing. For the entire dura	ation of the rescue op-	
	eration, the leve	crossing was ref	erred to with incorrect name	s. At their worst, such	
	location problem	is can lead to tre	atment procedures being de	elayed, with fatal con-	
	sequences.		1 5	,	
	A variety of op	erators should c	levelop systems and impl	ement equipment to	
	facilitate location	on of an acciden	t site.		
Date	Status	Comments			
18.8.2011	In progress	Markings on t	rack to demote the location	will be improved.	
9.2.2012	In progress				
19.9.2013	In progress	Emergency F	Response Centre, VR Gro	oup Ltd and Finnish	
		Transport Age	ency in co-operation are dra	fting the procedure of	
		best practises	. Next meeting last part of t	his year.	
10.3.2014	In progress	Emergency F	Response Centre, VR Gro	oup Ltd and Finnish	
		Transport Age	ency in co-operation are dra	fting the procedure of	
		best practises	· ·		
25.2.2015	Under implemer	- Will be handl	ed in the meeting of Finnis	sh Transport Agency,	
	tation .	Emergency R	esponse Centre and VR Gr	oup Ltd.	
3.3.2016	Under implemen	- Finnish Trans	port Agency, Emergency F	Response Centre and	
	tation	VR Group Ltd	are working with the issue.		
28.3.2017	Under implemen)-			
	tation				

Annex 1/7 (28)

11.4.2018	Partly imple- mented	Rolling stock has GPS based positioning system. Commission- ing of the new ERICA system at emergency response centres has been delayed.
25.3.2019	IMPLEMENTED	Automatic location of emergency calls is in operation for calls made through 112Suomi-application and also through AML- emergency location function that is in all Android-phones and most iOS-phones. Finrail has taken into use YKÄ-application that displays locomotive drivers KUPLA-terminal location to traf- fic controllers. Railway operators have updated their instruc- tions to include these new functions.

Date and time (Code):	1991–2010				
Location:	Finland				
Type of occurrence:	Level crossing ac	cidents			
Train type and number:					
Road vehicle:					
		In the train	In the road vehicle		
Persons on board:	Crew:				
	Passengers:				
Fatally injured:	Crew:				
	Passengers:				
Seriously injured:	Crew:				
	Passengers:				
Slightly injured:	Crew:				
	Passengers:				
Damages of rolling stock:					
Damages on track equipment:					
Other damages:					
Summary: While the number of le	evel crossing accic	lents in Finland reduce	d significantly between 1991		
nd 1998, since then the number has remained constant and, at times, has even increased slightly. The					

and 1998, since then the number has remained constant and, at times, has even increased slightly. The number of accidents has fallen in the last two years. However, this has not influenced the number of deaths. Since 1993, there has been an average of 10 fatalities per year in level crossing accidents. Compared to other European countries, level crossing safety in Finland is below average.

Some 78 per cent of all fatal accidents occurred on level crossings without warning devices. Accidents on level crossings of this type were generally caused by the vehicle driver misjudging the situation, not by the driver taking unnecessary risks. The road speed limit was typically 80 km/h and the railway speed limit 120 km/h. Most level crossings without warning devices are located on private roads and most fatal accidents occurred on level crossings on such roads. Nearly all level crossings without warning devices fail to meet the related railway regulations. Maintainers of private roads do not have sufficient information on their level crossing maintenance obligations.

Based on statistical analysis, a dangerous level crossing is one without warning devices, with a low road speed limit, and with a high amount of average daily traffic. Such level crossings are typically located in residential areas.

Final report issued	d: 13.2.2012		
Recommendation	Practice has shown that the rate of removal and securing level crossings is gov-		
NI. 5509		is granted by the Panalitent. The level crossing strategy should	
	be accorded greate	er importance by moving it under the ministry of Transport and	
	Communications, v	which might ease acquisition of the required resources.	
	A new strategy sl	hould be drawn up to improve level crossing safety, and a	
	concrete plan wit	th funding arrangements should be drafted based on this	
	strategy.		
Date	Status	Comments	
19.9.2013			
10.3.2014	In progress		
25.2.2015	Under implemen-		
	tation		
3.3.2016	Under implemen-	Transport Agency has begun the operation definition of policy.	
	tation .		
28.3.2017	Under implemen-	Financing for the realisation of the strategy is missing.	
	tation		

Annex 1/8 (28)

11.4.2018	Partly imple-	New level crossing safety plan has been issued in 2018 and		
25.2.2010		auunonai futuiny for it has been yfanteu.		
25.3.2019		Implemented differently: Ministry of transport has issued a plan		
		to improve level crossing safety during years 2018-2021. Finn-		
		funded from additional budget		
Bacammandation	Doilwov octore how	runded from additional budget.		
	According to V/TT's	e no common database for accidents and dangerous situations.		
NI. 3312	tems of the railway company, the Finnish Transport Agency, and the Finnish			
	Transport Safety A	aprov Merging these accident databases is recommended		
	A single and com	A single and common accident and deviation database for all those operation		
	the railway syster	n in Finland should be created.		
Date	Status	Comments		
19.9.2013	In progress	Trafi will in future hold a common database.		
10.3.2014	In progress	Trafi will in future hold a common database. Will be ready in		
		2014.		
25.2.2015	Under implemen-	Nearly ready.		
	tation			
3.3.2016	Under implemen-	Ready in 2016.		
00.0.0017	tation	Detahara washi ta tasta		
28.3.2017	under implemen-	Database ready to tests.		
11 4 2019	lation	Will be apprectional at the beginning of year 2010		
11.4.2010	tation	win be operational at the beginning of year 2019.		
25 3 2010		The recommendation 2016-S12 deals with the same matter		
Pecommondation	The Koululiity soft	ware which evaluates the dangers of school routes, does not		
Nr S314	include level cross	ings, because the road database information used by the soft-		
11.0014	ware does not cont	tain level crossing information		
	When planning	school transportation the municipalities should improve		
	safety by avoiding level crossings without warning devices along the routes.			
	ι δαίτιν μν ανυιμίι	u level clossinus wilnoul warning devices along the roules.		
Date	Status	Comments		
<i>Date</i> 19.9.2013	Status In progress	Comments		
Date 19.9.2013 10.3.2014	Status In progress In progress	Comments		
<i>Date</i> 19.9.2013 10.3.2014 25.2.2015	Status In progress In progress Under implemen-	Comments		
<i>Date</i> 19.9.2013 10.3.2014 25.2.2015	Status In progress In progress Under implemen- tation	Comments		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016	Status In progress In progress Under implemen- tation Under implemen-	Comments Developed geographic information system.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016	Status In progress In progress Under implemen- tation Under implemen- tation	Comments Developed geographic information system.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple-	Comments Developed geographic information system. School transport guide will be updated in 2018. Recommenda-		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented	Comments Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation	Comments Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation	Comments Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description of the inquiry.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level crossing crossings percentil	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. perceptivity was also noted in VTT's research. To make level pla sufficiently early for road users and to answer correct level		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use:	Comments Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description of the inquiry of the inquiry of the inquiry. Description of the inquiry of the i		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use: Ways of improvin	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description of the inquiry of the inquiry. Description of the inquiry of the		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use: Ways of improvin use and technical	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description of the inquiry. Description of the inquiry of level crossings without warning description of the inquiry of level crossings and their conditions of properties should be specified.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossing crossings perceptil crossing use: Ways of improvin use and technical Status	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description of the inquiry of the inquiry. Description of the inquiry of t		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 Date 19.9.2013	StatusIn progressIn progressUnder implementationUnder implementationPartly implementedUnder implementedIn progress	Developed geographic information system. Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. will be sufficiently early for road users and to ensure correct level g the perceptivity of level crossings and their conditions of properties should be specified. Comments Researches made and also on going.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 Date 19.9.2013 10.3.2014	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use: Ways of improvin use and technical Status In progress In progress	Developed geographic information system. Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Dessing accidents occurred at level crossings without warning deng perceptivity was also noted in VTT's research. To make level be sufficiently early for road users and to ensure correct level g the perceptivity of level crossings and their conditions of properties should be specified. Comments Researches made and also on going.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 19.9.2013 10.3.2014 25.2.2015	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use: Ways of improvin use and technical Status In progress Under implemen- tation	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description Description Description Description Description School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description Descriptio		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 19.9.2013 10.3.2014 25.2.2015	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level crossing crossings perceptil crossing use: Ways of improvin use and technical Status In progress In progress Under implemen- tation Under implemen- tation	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description of the inquiry of the interpretent of the inquiry. Description of the inquiry of the interpretent of the inquiry. Description of the inquiry of the interpretent of the inquiry. Description of the inquiry of the interpretent of the inquiry. Description of the inquiry of the interpretent of the inquiry. Description of the inquiry of the interpretent of the inquiry. Description of the inquiry of the interpretent of the inquiry. Description of the inquiry of the inquiry. Description of the inquiry. Description of the inquiry. Descripti		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 19.9.2013 10.3.2014 25.2.2015	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use: Ways of improvin use and technical Status In progress Under implemen- tation Under implemen- tation	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Dessing accidents occurred at level crossings without warning deng perceptivity was also noted in VTT's research. To make level ble sufficiently early for road users and to ensure correct level g the perceptivity of level crossings and their conditions of properties should be specified. Comments Researches made and also on going. Project for means to improve perceptivity is in progress.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 19.9.2013 10.3.2014 25.2.2015	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use: Ways of improvin use and technical Status In progress In progress Under implemen- tation Under implemen- tation Under implemen- tation	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Dessing accidents occurred at level crossings without warning deng perceptivity was also noted in VTT's research. To make level ble sufficiently early for road users and to ensure correct level g the perceptivity of level crossings and their conditions of properties should be specified. Comments Researches made and also on going. Project for means to improve perceptivity is in progress.		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 19.9.2013 10.3.2014 25.2.2015	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossing crossings perceptil crossing use: Ways of improvin use and technical Status In progress Under implemen- tation Under implemen- tation Under implemen- tation	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description Description Description Description School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description Descriptio		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level cro vices. Level crossin crossings perceptil crossing use: Ways of improvin use and technical Status In progress Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description Description Description Description School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description Descriptio		
Date 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 25.3.2019 Recommendation Nr. S316 19.9.2013 10.3.2014 25.2.2015 3.3.2016 11.4.2018 11.4.2018	Status In progress In progress Under implemen- tation Under implemen- tation Partly imple- mented Under implemen- tation Most fatal level crossing crossings perceptil crossing use: Ways of improvin use and technical Status In progress In progress In progress Under implemen- tation Under implemen- tation Under implemen- tation Under implemen- tation Partly imple- mented	Developed geographic information system. School transport guide will be updated in 2018. Recommendation will be added as a part of designing new school transports. No answer to the inquiry. Description Description Signa accidents occurred at level crossings without warning deng perceptivity was also noted in VTT's research. To make level be sufficiently early for road users and to ensure correct level be sufficiently early for road users and to ensure correct level be sufficiently early for road users and their conditions of properties should be specified. Comments Researches made and also on going. Project for means to improve perceptivity is in progress. Project for means to improve perceptivity is in progress. Finnish Transport Agency will define measures for improving visibility of level crossings. Focus is on developing and installing		

Annex 1/9 (28)

25.3.2019 Partly imple- mented	Finnish transport agency has studied available solutions and started procurement of warning devices. Planned delivery was during years 2020-2021, but process has been delayed and is now in commercial court.
-----------------------------------	---

Date and time (Co	de):	21.2.2011, 4.05 (E	31/2011R)			
Location:		Nokia, between Siuro and Suoniemi stations				
Type of occurrence	e:	Collision of trains, rear end collision				
Train type and number:		Freight train 3811.	Freight train 3811 Sr1 electric locomotive and 21 wagons – Freight			
		train 3801, 2 Dv12	diesel locomotive and 24 w	adons		
Road vehicle:		-				
			In the train	In the road vehicle		
Persons on board		Crew:	1 – 1			
	-	Passengers:	0			
Fatally injured:		Crew:	1-0			
		Passengers:	0			
Seriously iniured:		Crew:	0			
		Passengers:	0			
Slightly injured		Crew:	0			
		Passengers:	0			
Damages of rolling	a stock	Sr1 electric locom	ptive and two timber wadon	s were hadly dam-		
Damages of Tomin	y 3100K.	aned		s were badiy dam		
Damages on track	equinment	Some sleepers we	re damaged			
Other damages	equipinent.	None	re damaged.			
Summary: A froigh	t train which h	none.	another freight train travelli	a to Mäntyluoto, Pori		
collided with the end of the other tra- 2011. The engine driver of the assistive, which collided the end of the cone wagon was badly damaged, accident site was interrupted for 14		ain in Nokia, betwee isting train fatally inj other train, were bac but was still repair 4 hours.	an Siuro and Suoniemi, at 4. Jured in the accident. One willy damaged and had to be sable. The tracks were unda	05 am on 21 February vagon and the locomo- scrapped. Additionally, amaged. Traffic at the		
braking at a speed	1 of 46 km/h fi	ve seconds before the impact. The train speed was 43 km/b upon				
impact The maxim	um permitted s	beed of the train which collided was 50 km/h.				
The accident was c	aused by the e	rroneous location ir	formation of the train to be	assisted		
Final report issued: 20.2.2012						
Recommendation	Determining t	he location of trains	is a challenging task. In ac	dition to the improved		
Nr S321	instructions cu	irrently in use.				
	A satellite lo	cation system should be implemented as quickly as possible to				
assist in loca		tion				
Date	Status	Comments				
19 9 2013	In progress	Emergency	Response Centre VR Gr	oun Ltd and Finnish		
10.0.2010	in progress	Transport Ad	ency in co-operation are dra	afting the procedure of		
		hest practises	Next meeting last part of	this vear		
10 3 2014	In progress	Emergency	Response Centre VR Gr	oun 1 td and Finnish		
		Transport Ag	ency in co-operation are dra	afting the procedure of		
		best practises	S.			
25.2.2015	Under implem	en- Will be hand	ed in the meeting of Finni	sh Transport Agency		
20.2.2010	tation	Emergency R	esponse Centre and VR G	roup I td		
3 3 2016	Under implem	en-				
0.0.2010	tation					
11 4 2018	Partly imple-	Rolling stock	has GPS based positioning	system Commission-		
11.4.2010	mented	ing of the nev	w FRICA system at emerge	ancy response centres		
	montou	has been dela	aved			
25.3.2019	IMPLEMENTI	ED Automatic loc made throug emergency lo most iOS-pho that displays l fic controllers	cation of emergency calls is h 112Suomi-application ar ocation function that is in a ones. Finrail has taken into ocomotive drivers KUPLA-to a. Railway operators have	s in operation for calls ad also through AML- II Android-phones and b use YKÄ-application erminal location to traf- updated their instruc-		
		tions to includ	le these new functions.			

Annex 1/10 (28)

Recommendation	The visibility of wagons should be improved. In the reconstruction drive, it was found that a wagon without a reflector on the end can only be seen from a short distance		
111.0020	in darkness.		
	Reflectors should be installed on the ends of wagons.		
Date	Status	Comments	
19.9.2013	In progress	Belongs also to the needs of shunting areas.	
10.3.2014	In progress	VR Ltd regards the realisation as challenging.	
25.2.2015	Under implemen-	3400 wagons are installed with reflectors; work is not yet ready.	
	tation		
3.3.2016	Under implemen-	In realisation: in the new wagons and 1/4 of the old wagons al-	
	tation	ready have.	
28.3.2017	Under implemen-		
	tation		
11.4.2018	Partly imple-	75% of freight wagons owned by VR Group have been fitted	
	mented	with end reflectors.	
25.3.2019	Partly imple-	VR is installing reflectors to freight wagons. 75% of freight wag-	
	mented	ons owned by VR Group have been fitted with end reflectors.	

Date and time (Co	de):	14.1.2012, 0.15 (R2012-01)		
Location:		Kouvola freight traffic railway yard		
Type of occurrence:		Derailment		
Train type and nur	nber:	Freight train 2032,	Sr1 electric locomotive and	35 wagons
Road vehicle:		-		0
			In the train	In the road vehicle
Persons on board		Crew:	1	
	ľ	Passengers:	0	
Fatally injured:		Crew:	0	
		Passengers:	0	
Seriously injured:		Crew:	0	
		Passengers:	0	
Slightly injured:		Crew:	0	
	F	Passengers:	0	
Damages of rolling	y stock:	Two derailed wago	ns sustained minor damage	Э.
		40 metres of rail we	ere damaged. Turnout 730,	the electric railway
Damages on track	equipment:	portal and the elect	ric cables for seven tracks	were damaged.
Other damages:		A signal post fell do	own.	
Summary: An acci	dent occurred	in the Kouvola freight traffic vard at 00.15 hrs on 14 th January 2012		
when two wagons o	f a departing fre	eight train were derailed immediately after their departure. One of the		
derailed wagons str	uck a signal po	ost, which collapsed onto an electric railway portal ten minutes later.		
The electrical cable	s for seven trac	cks were brought do	own by the portal's collapse	e. No personal injuries
resulted.		-		
The accident was ca	aused by a stop	block left under th	e train. Difficult weather co	nditions and darkness
made it difficult to s	ee the stop blo	ock. Additionally, th	e brake tester responsible	for removing the stop
block decided to pe	rform an extra	shunt on the train in	place of standard procedu	res, because the train
had moved too far a	alongside the sh	nunting signal.		
Final report issued	1: 24.9.2012			
Recommendation	It was found in	n the investigation th	hat the railway yard work in	structions do not take
Nr. S327	account of all	situations arising d	uring normal work. Instruct	tions for safety-critical
	operations sho	ould be presented a	s a checklist, in order to ma	ake work as standard-
	ised and unifo	orm as possible, ins	tead of working from mem-	ory. A checklist would
	help to avoid a	a situation where iss	ues are forgotten.	
	The railway yard work instructions should be developed in order to take ac-			
	count of all situations arising from normal work. Safety-critical instruction should be presented as a checklist.			-critical instructions
Date	Status	Comments		
19.9.2013	In progress	In a different v	way.	
10.3.2104	In progress	Guidelines wil	I be gone through in this ye	ar.
25.2.2015	Under implem tation	en- Instruction an	d training; nearly ready.	

3.3.2016	Under implemen- tation	Instructions renewed.
28.3.2017	Under implemen- tation	
11.4.2018	Under implemen- tation	Responsibility for railway yard instructions should in future be assigned to infrastructure manager therefore that there will be several operators at railyards.
25.3.2019	Under implemen- tation	Development of rail yard instructions has been started in Finn- ish transport agency and in railway stakeholders common in- struction work group.

Data and time (Code)	LC 4 2012 2 22 (Pr		
Date and time (Code).	0.4.2013, 3.22 (RZ	2013-01)	/
Location:	Vammala railway y	ard	
Type of occurrence:	Derailment		
Train type and number:	Freight train 3703,	Sr1 electric locomotive and	43 wagons
Road vehicle:	-		
		In the train	In the road vehicle
Persons on board:	Crew:	1	-
	Passengers:	0	-
Fatally injured:	Crew:	0	-
	Passengers:	0	-
Seriously injured:	Crew:	0	-
	Passengers:	0	-
Slightly injured:	Crew:	0	-
	Passengers:	0	-
Damages of rolling stock:	13 wagons damaged.		
	Two tracks were da	amaged at a distance of 177	7 metres, including
Damages on track equipment:	two turnouts. In adv	dition, the sleepers of one tr	rack were damaged
	at a distance of 249 metres.		
Other damages:	A small amount of crude tall oil leaked onto the ground.		
Disturbances of traffic:	The accident caused a traffic interruption that lasted approximately		
	11 hours. The stat	ion was returned to normal	l use one month after
	the accident. 11 tr	ains in passenger traffic ar	nd 11 trains in freight
	traffic had to be car	ncelled.	

Summary: Freight train 3703 en route from Tampere to Rauma derailed at the Vammala station in Sastamala. The train was proceeding as planned, until at the Vammala turnout V003, the rear bogie of wagon 15 or the front bogie of wagon 16 was directed between the switch blades and the stock rails of the turnout. As a consequence, the rear end of the train began to derail. Two Russian tank wagons tipped over and the train broke into two parts. Nine Finnish freight wagons derailed. The intermediate wagon between the Russian tank wagons and the Finnish freight wagons derailed to the left, causing minor damage to the track to the left of the train's direction of travel. The 16 wagons at the end of the train remained on the rails. The front end of the train, the locomotive and 15 wagons continued moving for another 314 metres after the brake pipe was broken. The rear bogie of the last wagon at the front end of the train's speed at the moment of derailment was 67 km/h.

The derailment was caused by the switch turning underneath the train. The train caused the open switch blade to move, resulting in the opening of the switch lock, which allowed the switch to turn. When an open switch blade is subjected to vibration or sufficiently powerful impacts, a switch lock that allows trailing may become unlocked. As a result, the closed switch blade opened, and the wagon wheels fell between the switch blade and the stock rail.

Final report issued	d: 20.2.2014			
Recommendation	The log data available in the railway safety system had not been examined and			
Nr. S338	analysed.	analysed.		
	The Finnish Tran	sport Agency should establish a system and methodology		
	for the analysis of the error logs of safety systems to ensure that repeated			
	flaws endangering safety are detected.			
Date	Status	Comments		
25.2.2015	Under implemen-	Fault situations will be recorded in the POHA system.		
	tation			

Annex 1/12 (28)

3.3.2016	Under implemen-	The instruction is being prepared.
	tation	
28.3.2017	Under implemen-	
	tation	
11.4.2018	Under implemen-	Track and safety equipment repair, and measurement data will
	tation	be integrated to a single system in RAID-E project.
25.3.2019	Partly imple- mented	The development project of the condition control of the track network and of maintenance systems (RAID-E) improves the matter but because of different generations of equipment, all the equipment cannot be connected to the system.

Date and time (Cod	de): 7.11	.2013. 17.17 (R2013-02)	
Location:	Pän	Pännäinen. Seinäioki Ylivieska section of line		
Type of occurrence	e: Trai	Train collision. Collision with an obstacle, a maintenance machine.		
Train type and num	nber: Frei	Freight train 5489, 2 Dv12 diesel locomotives and 6 wagons.		
Road vehicle:	-	J		
			In the train	In the road vehicle
Persons on board:	Cre	w:	1+1	-
	Pas	senaers:	0	_
Fatally injured	Cre	w [.]	0	_
	Pas	senaers:	0	_
Seriously injured	Cre	w [.]	0	_
	Pas	senaers:	0	_
Slightly injured	Cre	w [.]	0 + 1	
onginay injurcu.	Pas	sonaors'	0	
Damages of rolling	stock: The	collision cause	d a hole into the fuel tank o	f the first engine and
Damayes or roming	the	left stops of bot	h engines were damaged	The excevator was
	dam	and hevend r	engines were damaged.	THE EXCAVATOR Was
Domogos on trock	aquinmont: Non		epan.	
Other demogra		titors fuel looks	d onto the track	
Disturbances of tr		fie of the poold	a onto the track.	E houra Dolova from
Disturbances of the	anic. Ital	to four hours	for eight percentage trains	and offects on coverel
	nou	r traing boodur	o of waiting One fraight tra	in was cancelled from
	bety	other trains because of waiting. One freight train was cancelled from		
Summorus Freight	train 5490 collider	ided with an exception carrying out trackwork on the track section		
botwoon Dönnöinon	and Koloni on w	with an excav	ature and electrification w	on the track section
between Pannainen and Kolppi, on which super		nich superstru	rk supervisor bad requeste	of the traffic controller
for permission for an executor to		/ out trackwork	The permission was giver	for the work to begin
for permission for an excavator to		ind a freight tra	in" The trackwork supervise	or informed the exca-
vator driver of the permission. At t		ime the excav	ator was located 3.4 kilom	etres from Pännäinen
Station towards Kolr	ni			
Having driven the ex	cavator partially or	nto the track th	e driver noticed the lights o	f an approaching
train and immediate	v attempted to get (off the track On	ly moments earlier the end	ine driver had realised
that signal P523 had	been switched to	display Stop ar	nd had begun emergency b	raking from the speed
of 50 km/h. Howeve	r the locomotive's	left buffer hit th	he left rear corner of the ex	cavator's top carriage
and the locomotive's	s lower part hit the	rear left corner	of the excavator's undercar	riage
Final report issued	<i>I</i> : 11.11.2015			
Recommendation	In addition to their	normal worklos	ad trackwork supervisors m	av he responsible for
Nr S343	requesting trackwo	rk permissions	s for several teams. This d	isrupts their focus on
	their own tasks an	d endangers tr	ackwork safety Allocation	of sufficient time and
	opportunities for tra	ackwork superv	isors to focus on the traffic s	afety functions should
	be ensured in each trackwork project			
	The Finnish Tran	sport Agency	will ensure that trackwor	k supervisors focus
	on their traffic safety function and develop better tools for trackwork supervisions for sors for ensuring safety.			r trackwork supervi-
Date	Status	Comments		
25.2.2015	Under implemen-	In the safety in	nstructions is entered the ma	aximum number of the
	tation	teams for trac	k work supervisor: in the fu	ture GPS locating.
3.3.2016	Under implemen-	Project started	d.	
	tation			

28.3.2017	Under implemen-	
11 1 2010	tation Double imple	New DLIMA employed an has been taken in to use 10.0.2010. It
11.4.2018	Partly imple-	New RUMA-application has been taken in to use 12.6.2018. It
	menteu	map based user interface that is also visible to traffic control-
		lers
25.3.2019	IMPLEMENTED	RUMA-application for track work has been in use since June
201012010		2018.
Recommendation	Currently, trackwor	rks begin without sufficient preparation and clarification of the
Nr. S345	parties' responsibili	ities. Initial safety meetings are held in an attempt to ensure that
	the safety aspects	are put right in order for the contractors to begin work. However,
	much more time sh	nould be devoted to such preparation, planning and clarification
	of responsibilities.	Good planning also involves ensuring that communication be-
	tween the parties is	s working.
	and sufficient time	sport Agency will ensure that contracts include a separate
	before trackwork	is begun.
Date	Status	Comments
25.2.2015	Under implemen-	In March workshop of track possession planning.
	tation	· · · · · ·
3.3.2016	Under implemen-	Tested in Seinäjoki–Oulu project.
	tation	
28.3.2017	Under implemen-	
44.4.0040	tation	The set 10 is the supervised to see all the
11.4.2018	Under implemen-	i ne will is to proceed towards this.
25.3.2010	Partly imple-	Track work meetings are widely in use in the whole of Finland
25.5.2019	mented	The handling of track work is systemised in the regional quality
	montou	and track work meetings concerning traffic. The procedures will
		be unified during 2019.
Recommendation	Instructions issued	by the Finnish Transport Agency define the parties' responsibil-
Nr. S346	ities and tasks rela	ted to the safety of railway operations. The instructions empha-
	sise monitoring wh	ere written forms and reports are used. With the exception of
	commissioning ins	pections, site monitoring is rarely carried out on the field. The
	The large number	pliance with trackwork safety regulations should be increased.
	These occurrences	s can be reduced only by increasing field monitoring. An in-
	creased risk of get	ting caught for breaches of regulations efficiently directs the be-
	haviour of both org	anisations and individuals. Along with this measure, actions that
	comply with safety	regulations should be made financially attractive.
	The Finnish Trans	sport Agency will increase the field monitoring of trackwork
-	safety regulations	by allocating appropriate resources for such work.
Date	Status	Comments
25.2.2015	tation	Accepted in the management team; work underway.
3.3.2016	Under implemen-	Safety coordinator training underway.
	tation	
28.3.2017	Under implemen- tation	Piloted. Transport Agency tries to develop monitoring.
11.4.2018	Under implemen-	Guide book for supervisors is being prepared. Rail maintenance
	tation	supervision instruction is ready. Minimum requirements for su-
		pervision will be defined during 2018.
25.3.2019	Under implemen-	Finnish transport agency has improved instructions and pro-
	101.00	
	tation	curement process. Supervision criteria will be defined in all fu-

Date and time (Code):	18.3.2015, 14.58 (R2015-03)
Location:	Hyvinkää, Helsinki Riihimäki section of line (line number 112), km 61+293
Type of occurrence:	Incident, risk of derailment

Annex 1/14 (28)

Train type and nur	umber: (Commuter train 9692, 2 x Sm4 electric train units			
Road vehicle:		-				
		<u> </u>		In the train		In the road vehicle
Persons on board	:	Crev	N:	2		-
		Pase	sengers:	100		
Fatally injured:		Crev	N:	0		-
		Pass	sengers:	0		-
Seriously injured:		Crev	N:	0		-
		Pass	sengers:	0		-
Slightly injured:		Crev	N:	0		-
		Pass	sengers:	0		-
Damages of rolling	g stock:	None	ә.			
Damages on track	equipment:	None	ә.			
Other damages:		None	None.			
Disturbances of tr	affic:	None	ə			
Summary: The reg kilometers before t 156 km/h. The maxi been switched on. the rear unit reporte overhead rack fell o	gional train (the he Hyvinkää s mum allowed s The incident dic ed having faller in the floor and	R tr tatior peed not n off brok	ain) had depar 1, at 2.58 p.m 1 over the switc cause signification the seat due t e.	rted the Riihimäki ., the train ran th :h was 80 km/h. Th ant personal injurie o a strong lurch. I	station at irough a s he engine' es. One pa Loose fluo	2.52 p.m. About two switch at a speed of s ATP device had not assenger travelling in prescent tubes on the
Final report issued	d: 7.8.2015					
Recommendation Nr. 2015-S15	If the ATP eng should give th Finland recom implementatio Cabin equipm	gine of ie enginmen imen in of t nent	device is not so gine driver a c ds that the Fin the following re should give t	witched on or it m lear warning. The inish Transport Sa commendation: the engine driver	alfunction Safety In afety Ager	s, a cabin equipment westigation Authority, ncy (Trafi) ensure the warning if the train's
	ATP engine d	levic	e is not opera	ting.		
Date	Status		Comments	· · · ·		
3.3.2016	Under implementation	en-	The realisation	n decision made; o	completed	l 2017.
28.3.2017	Under implem tation	en-	For VR it will b already it.	e carried out durir	ng the year	r 2017. Fenniarail has
11.4.2018	Partly imple- mented		Implemented on driver's de and in some, applied to obs	differently: Some i sk, some limit ma warning is generat solescent rolling st	rolling stoo aximum sp ted in train ock.	ck has warning lamps beed if ATC is not on a software. Will not be
25.3.2019	IMPLEMENTE	∃D	Implemented is automatical In Helsinki City is ATC is not VR Group's n and speed is to alert driver Dv12 locomot	differently: In Fenn ly limited if ATC is y Transport's Sm5 operative and spec- ew Sr3 locomotive limited. VR has ins if ATC is not opera- tives.	iarail's Dr not opera trains ther ed is also es have al stalled sep ative to old	18 locomotives speed ative. re is an alarm to driver limited. Iso an alarm to driver parated warning lights er rolling stock except
Recommendation	Since the acc	ident	risk of an ope	rating train increa	ses if its /	ATP engine device is
Nr. 2015-S16	not switched on, the maximum speed of the train should be mechanically restrict in order to reduce the consequences of a possible accident. The Safety Investig tion Authority, Finland recommends that the Finnish Transport Safety Agency (Tra- ensure the implementation of the following recommendation: If a train's ATP engine device is not switched on, the train's speed should restricted to a maximum of 80 km/h.		echanically restricted The Safety Investiga- Safety Agency (Trafi) n's speed should be			
Date	Status	!	Comments		<u>.</u>	
3.3.2016	Under implem tation	en-	Will be only in	the new Sr3 loco	motives.	
28.3.2017	Under implem tation	en-	VR's rolling st alreadv has.	tock only in the ne	ew Sr3 lo	comotives. Fenniarail
11.4.2018	Under implem tation	en-	Implemented	into some series c	of rolling st	tock.
25.3.2019	Under implem	en-	In Fenniarail's	Dr18 locomotive:	s speed is	automatically limited
	tation		if ATC is not c	operative.		

		In Helsinki City Transport's Sm5 trains speed is also limited if ATC is not operative.		
		In VR Group's new Sr3 locomotives speed is limited if ATC is		
		not operative. VR has not decided to make modifications to other rolling stock.		
Recommendation	The current safety	management system and engine driver training have a scarcity		
Nr. 2015-S19	of content related	to the mastery of human factors. These include, for instance,		
	maintaining situation	onal awareness during the performance of one's work, recovery		
	from shocking situa	ations, and learning from deviations. The Safety Investigation Au-		
	thority, Finland rec	commends that the Finnish Transport Safety Agency (Trafi) en-		
	sure the implement	tation of the following recommendation:		
	The Finnish Trans	The Finnish Transport Safety Agency (Trafi) should demand that the subject		
	matter of human f	factors will be emphasised more in both the safety manage-		
	ment systems of I	railway operators and training in the field.		
Date	Status	Comments		
3.3.2016	Under implemen-	Trafi arranges the cooperation forum.		
	tation			
28.3.2017	Under implemen-	In progress.		
	tation			
11.4.2018	Under implemen-	Regulation for contents of safety management system will be		
	tation	renewed as part of implementation of EU 4 th railway package.		
25.3.2019	IMPLEMENTED	New EU-regulations for including human factors into safety		
		management systyems have been in use since 16.6.2018. In		
		Finland HF-network for railways promotes subject. Traficom		
		has also issued a HOF-quide.		

Date and time (Code):	6.2.2015, 9.14 (R2	2015-01)		
Location:	Kokemäki, Isotalo I	level crossing (km 285+145), Kokemäki Pori sec-	
	tion of line (line nur	tion of line (line number 344)		
Type of occurrence:	Level crossing acci	ident, passenger train-tract	or	
Train type and number:	Passenger train 46	1, Sr1electric locomotive ar	nd 3 coaches	
Road vehicle:	Articulated Hauler	(Dumper), Volvo A25D, 200	2 model	
		In the train	In the road vehicle	
Persons on board:	Crew:	2	1	
	Passengers:	25	0	
Fatally injured:	Crew:	0	0	
	Passengers:	0	0	
Seriously injured:	Crew:	1	1	
	Passengers:	0	0	
Slightly injured:	Crew:	0	0	
	Passengers:	0	0	
Damages of rolling stock:	Locomotive front was damaged, the dumper was broken from its ar-			
	ticulation.			
Damages on track equipment:	None.			
Other damages:	None.			
Disturbances of traffic:	Traffic at the accident site was interrupted for 7 hours. The train to			
	Pori was replaced	with bus. Three passenger	r trains from between	
	Tampere–Pori were	e replaced with busses.		

Summary: On Friday, 6 February 2015, a passenger train and an articulated hauler collided in Kokemäki. The collision occurred at the unprotected level crossing of a private road and the Kokemäki–Pori railway. The accident happened while workmen were preparing to move a track excavator over the track. The driver of the articulated hauler was driving over the tracks to transport materials required for moving the excavator, when the passenger train came from his left and collided with the trailer of the articulated hauler driver and engine driver were seriously injured. The articulated hauler is a 21-tonne earthmoving machine. The impact split the hauler in two, the tractor being thrown to the left side of the tracks and the trailer to the right side. The front end of the locomotive was badly damaged. The collision caused no damage to the track. The costs of repairs to the train engine and articulated hauler amounted to about EUR 700,000.

Final report issued: 19.8.2015

Annex 1/16 (28)

Recommendation Nr. 2015-S23	The railway maintenance provider issued appropriate instructions to the work su- pervisors of the earthworks company for how to move the excavator over the tracks. For this purpose, the maintenance provider adapted the trackwork safety instruc- tions, as there are no separate instructions available for non-trackwork-related use of level crossings in exceptional circumstances that pose a risk of collision. The Safety Investigation Authority, Finland recommends that the Finnish Transport Safety Agency should ensure the adoption of the following recommendation: The Finnish Transport Agency must draft readily available guidelines for time- intensive, non-trackwork-related use of level crossings or other similar work		
Date	Status	Comments	
3.3.2016	Under implemen- tation	Need for new instructions will be taken into account when pre- paring the next action plan.	
28.3.2017	Under implemen- tation	It has been dealt with different actors. Actors must learn to es- timate.	
11.4.2018	Partly imple- mented	Guide book for special road transports in level crossings will be published in 2018.	
25.3.2019	Partly imple- mented	Instructions for special road transports in level crossings have been published 1.1.2019. Instructions for other time-consuming rail crossing will be finished during 2019.	
Recommendation Nr. 2015-S24	According to Section 88 of the Road Traffic Act, the use of seatbelts in work ma- chines and tractors is not mandatory. In this accident, the articulated hauler driver would probably have suffered less severe injuries if he had worn a seatbelt. Seat- belts should be used in tractors and work machines at least when driving in general traffic. The Safety Investigation Authority issues the following recommendation to the Ministry of Transport and Communications: The Road Traffic Act must stipulate that those operating tractors and work		
Date	Status	Comments	
3.3.2016	Under implemen- tation	The tractors which have seat belt will come within the sphere of the use duty. One cannot require to the old tractors in which have no belts.	
28.3.2017	Under implemen- tation	This is in the amendment of the road traffic act which is on the statement.	
11.4.2018	Under implemen- tation	Mandatory use of safety belt in tractors is included in legislative proposal.	
25.3.2019	IMPLEMENTED	Implemented differently: In new road legislation (in force 1.6.2020) use of safety belt is will be mandatory in tractors and motorised work machines. However, the seat belt does not need to be used when from the use of the seat belt there is a drawback in the work which is done with the vehicle.	

Date and time (Code):	12.3.2015, 13.19 (R2015-02)	
Location:	Oulunkylä, Helsinki	i–Riihimäki section of line (l	ine number 112),
	km 8.	-	
Type of occurrence:	Incident, risk of col	lision	
Train type and number:	Commuter train 96	76, 2 x Sm4 electric train u	nits – Commuter train
	9840, 2 x Sm4 elec	ctric train units.	
Road vehicle:	-		
		In the train	In the road vehicle
Persons on board:	Crew:	2 – 2	-
	Passengers:	50 - 50	-
Fatally injured:	Crew:	0	-
	Passengers:	0	-
Seriously injured:	Crew:	0	-
	Passengers:	0	-
Slightly injured:	Crew:	0	-
	Passengers:	0	-
Damages of rolling stock:	None.		
Damages on track equipment:	None.		

Other damages:	s: None.	
Disturbances of traffic:		ain fell behind its schedule for about 24 minutes and Z-train fell
	beh	nd its schedule about 15 minutes.
Summary: On Thu	rsday, 12 March 2	015 at 1.19 pm, an incident occurred at Pukinmäki Station after
two Sm4 commuter	trains ended up w	ithin the same block section. The incident occurred after the H
train stopped as a r	esult of a malfuncti	on in safety device on the neutral section following signal E581.
The engine driver le	t the train "roll" bac	kwards in order to exit the neutral section, causing it to enter the
block section of the	Z train following it o	on the same track. The H train ran late 24 minutes and the Z train
15 minutes. Other ra	ail traffic was not di	sturbed. The incident did not cause any damage.
Final report issued	: 22.10.2015	
Recommendation	In this case the fau	It of the safety device had not been repaired even though it had
Nr. 2015-S30	been signed repair	ed. In order that in the future the maintenance would know how
	to correct the right	faults:
	The maintainer o	f the rolling stock must ensure and instruct the repairs of
	safety device ma	-functions in the rolling stock better than at present.
Date	Status	Comments
3.3.2016	Under implemen-	VR will settle.
00.0.0047		
28.3.2017	Under implemen-	VR WIII Settle.
11 / 2018	Dartly imple	Has been applied partly in VP Group's intelligent maintenance
11.4.2010	mented	concept
25 3 2019	Under implemen-	VR has implemented for its part as a part of the developing of
20.0.2010	tation	the maintenance systems of the rolling stock (intelligent mainte-
	adon	nance)
Recommendation	The technical sup	port needed in the problem situations of Sm commuter trains to
Nr. 2015-S31	the engine drivers	has not been arranged equally well as with goods trains and
	long-distance traffi	c. The engine drivers even do not necessarily know where to ask
	for the technical s	upport and getting the support is not guaranteed all the times of
	day. To solve the p	problem:
	The technical sup	pport for the Sm commuter trains is moved to the VR Opera-
	tions Centre.	
Date	Status	Comments
3.3.2016	Under implemen-	Negotiations for an agreement unfinished.
	tation	
28.3.2017	Under implemen-	VR will move the technical support to transport control of local
	tation	traffic.
11.4.2018	Partly imple-	Commuter train driver's technical support has been moved to
05.0.0040	mented	operations control at Helsinki depot.
25.3.2019	IMPLEMENTED	Implemented differently: VR Commuter Traffic, that includes
		also HSL Commuter Traffic, has separate technical services for
		train drivers. This service will be kept separate from VR opera-
		tion centre, because services can this way be more specialised.

Date and time (Code):	2015 (R2015-S1)		
Location:	Finland		
Type of occurrence:	Wrong routings		
Train type and number:			
Road vehicle:	-		
		In the train	In the road vehicle
Persons on board:	Crew:		
	Passengers:		
Fatally injured:	Crew:		
	Passengers:		
Seriously injured:	Crew:		
	Passengers:		
Slightly injured:	Crew:		
	Passengers:		
Damages of rolling stock:			
Damages on track equipment:			

Annex 1/18 (28)

Other damages:			
Disturbances of tr	affic:		
Summary: The Sat	fety Investigation Au	thority investigated factors causing wrong routings in train traffic,	
by examining a nur	nber of selected ca	ses and going through all of the wrong routes formed in 2015,	
based on data mad	e available by the Fi	innish Transport Agency, Finrail and VR.	
Final report issued	d: 8.7.2016		
Recommendation	Around 80% of the	wrong routings were created manually. The use of train number	
Nr. 2016-S11	automation would I	have been possible in over half of these cases. The manual cre-	
	ation of routes is pr	rone to error.	
	The Finnish Trans	sport Agency should, in collaboration with Finrail Oy, ensure	
	that, as a general	rule, routes are created by the automated system.	
Date	Status	Comments	
28.3.2017	Under implemen-	Transport Agency and Finrail try to implement the recommen-	
	tation	dation.	
11.4.2018	Under implemen-	By improving situational traffic planning, use of automation can	
	tation	be increased in forming train routes.	
25.3.2019	IMPLEMENTED	Traffic controllers are trained and instructed to use primarily au-	
		tomatic functions when forming and securing routes. It is how-	
		ever necessary to make sure that they can also do the tasks	
		manually in case of system failures etc.3EHV62vuotta	
Recommendation	Not all wrong routin	as are reported, or their data is not collected, although this would	
Nr. 2016-S12	be possible throug	h IT means. No clear and uniform system exists for reporting on	
	wrong routings the	at covers all parties: the rail traffic operators, the owner of the	
	railway network an	d the safety authority. It is not possible to gain an overview of the	
	issue.	, , , , ,	
	The Finnish Tran	sport Safety Agency (Trafi) is obliged to create a uniform	
	system for the rep	orting and classifying of deviations; one covering all actors.	
Date	Status	Comments	
28.3.2017	Under implemen-	Trafi is making the system and soon it is possible to test.	
	tation		
11.4.2018	Under implemen-	Will probably be operational at the beginning of year 2019.	
	tation		
25.3.2019	Partly imple-	Traficom is working on a common incident reporting system. VR	
	mented	Group's and Finnis transports agency's incidents reports will be	
		transferred directly to the system. Smaller actors' incident re-	
		ports to the database by e-mail or with help of the network form.	
Recommendation	The rapid deregula	tion of national regulations and references to EU regulations has	
Nr. 2016-S13	lately created a situation, where detailed and practical regulations no longer exist.		
	National instruction	ns have been finished too late considering the adoption of the	
	regulations, resulting	ng in several postponements of their adoption. The time traffic	
	controllers have to	familiarise themselves with the instructions has been short. Reg-	
	ulations and instruc	ctions already rescinded have also been left in use.	
	The Finnish Tran	sport Agency (Trafi) must ensure that the instructions di-	
	rectly affecting the	e work of traffic controllers are kept up to date and that they	
	are not put into us	se without sufficient orientation of personnel.	
Date	Status	Comments	
28.3.2017	Under implemen-	I ransport Agency strives towards this.	
	tation		
11.4.2018	Under implemen-	Finnish Transport Agency has developed and taken into use a	
	tation	new system for controlling changes in instructions.	
25.3.2019	IMPLEMENTED	Finnish transport agency and Finrail have agreed procedures	
		and meeting structures to ensure sufficient communication and	
		coordination of system changes and commissioning of new sys-	
	O satisfies a	lems.	
Recommendation	Continuous change	es and the deployment of incomplete systems increase the work-	
Nr. 2016-S14	load of the traffic co	ontrollers.	
	Ine Finnish Iran	sport Agency must ensure that new systems or modifica-	
	tions to existing systems are not introduced incomplete, or without sufficiel		
Dete	Orientation of the	starr.	
	Status	Comments	
28.3.2017	ISSUED		

11.4.2018	Under implemen- tation	In RUMA-application that will be commenced in summer 2018 criteria for commissioning is clearly defined.	
25.3.2019	IMPLEMENTED	Finnish transport agency has established procedures for change management.	
Recommendation Nr. 2016-S15	Traffic controllers feel that they have insufficient say in the creation of new traffic control systems and the development of old ones. Defects that are the responsibility of the Finnish Transport Agency (such as defects in technical equipment) are corrected quickly, but deficiencies and development needs are not necessarily reacted to at all.		
	When procuring t take steps to ens be implemented s	raffic control systems, the Finnish Transport Agency must ure that any development needs emerging in a system can smoothly during the system's lifespan.	
Date	Status	Comments	
28.3.2017	Under implemen- tation	Transport Agency examines if it is working in Riihimäki–Tam- pere amendment work.	
11.4.2018	Partly imple- mented	Finish Transport Agency and Finrail have started regular meet- ings where among other topics the most critical development needs are discussed.	
25.3.2019	Partly imple- mented	Responsibility of system development is divided between Finn- ish transport agency and Traffic Management Finland Group (TMFG). Transport agency has agreed procedures for pro- cessing initiatives from traffic controllers. Initiative processing will be improved during 2019.	

Date and time (Co	ode): 3.2.2016, 8.09 (R2016-01)			
Location:		Uimaharju, (line nu	mber 701), km 673+930	
Type of occurrenc	e:	Accident to person	s involving rolling stock in r	motion – Track worker
		hit by a train.		
Train type and nur	nber:	Regional train 760,	Dm12 rail bus	
Road vehicle:		-		
			In the train	Other
Persons on board	:	Crew:	1	
		Passengers:	24	
Fatally injured:		Crew:	0	
		Passengers:	0	
Seriously injured:		Crew:	0	1
		Passengers:	0	
Slightly injured:		Crew:	0	
		Passengers:	0	
Damages of rolling stock:		None.		
Damages on track	equipment:	None.		
Other damages:		Portable earth rada	r was damaged.	
Disturbances of traffic:		Traffic at the accide	ent site was interrupted for	20 minutes.
Summary: The accident happene		d when one of the c	able markers did not notice	e the approaching train
and moved too clos	se to the rails.	The cable marker's	attention was focused on	the cable detector. In
addition, the curren	t weather condi	tions and the train b	being quiet made the train	more difficult to notice.
Due to the suddenn	ess of the situa	tion, the engine driv	ver had no chance to avoid	the collision.
Final report issued	d: 4.10.2016			
Recommendation	The Finnish T	ransport Agency's	cable marking request forr	n does not directly ad-
Nr. 2016-S27	dress the need	d for protective mea	asures during the work. Th	e instructions on cable
	marking do no	ot discuss work saf	ety sufficiently. At the mo	ment, there is a great
	variety among	cable marking requ	uests, cable marking reque	est forms are not used,
	and the responsibilities for using the forms are unclear.			
	The Finnish Transport Agency shall renew the instructions on cable ma		ons on cable marking	
	and adapt the cable marking request form so that the purchaser must		ourchaser must com-	
	ment on the protective measures to be used in the work.			
Date	Status	Comments		
28.3.2017	Under implementation	en- Not yet ready.		

Annex 1/20 (28)

11.4.2018	Under implemen-	Instructions will be updated during 2018.
	tation	
25.3.2019	Under implemen- tation	Finnish transport agency is updating cable detection form's commercial issues. Instructions for cable detection will be updated at the same time. New instructions clearly state that all cable detection work on railways is official track work and all trac work instructions must be followed.

Date and time (Co	de):	23.3.2016 (R2016	23.3.2016 (R2016-02)		
Location:		Finland			
Type of occurrence:		Train collision			
Train type and nur	nber:	Freight train 11375	Freight train 11375 – Sr1 electric locomotive		
Road vehicle:		-			
Persons on board		Crew:	Crew:	Crew:	
		Passengers:	Passengers:	Passengers:	
Fatally injured:		Crew:	Crew:	Crew:	
		Passengers:	Passengers:	Passengers:	
Seriously injured:		Crew:	Crew:	Crew:	
		Passengers:	Passengers:	Passengers:	
Slightly injured:		Crew:	Crew:	Crew:	
		Passengers:	Passengers:	Passengers:	
Damages of rolling	g stock:	Damages to the loc	comotive.		
Damages on track	equipment:	Damage to approxi	mately 250 meters of track	and track equipment.	
Other damages:		None.			
Disturbances of tra	affic:	There was interruption of three days in rail traffic in one lane of two			
		lane track. Totally closed for five hours.			
Summary: A locon	notive on its wa	ay from Kokkola to Ylivieska collided with a steel slit coil on the track			
at the speed of 120 km/h near the		Matkaneva Station. The locomotive jumped over the slit coil, which			
was lying on its flat	side, and becar	me derailed. After be	eing derailed, the locomotive	e travelled 185 metres	
and came to rest tilt	ed over the rig	ht rail so that the rai	I was close to the middle of	the locomotive.	
Final report issued: 20.2.2017					
Recommendation The breaking of the radial straps holding the slit coil pack together was preced		ether was preceded by			
Nr. 2017-S3	the radial stra	ps becoming loose	and displaced during the h	andling and transport	
	after they wer	e bound at the fact	tory. The loose radial strap	s allowed the slit coil	
	pack to tilt dur	ing transport. In ord	ler to ensure that the radial	straps are sufficiently	
	tight and that t	hey stay in place, th	e Safety Investigation Autho	prity recommends that:	
	SSAB specifi	ies the binding of	slit coil packs and verifie	es it by calculations,	
	taking the st	resses due to hand	dling at the factory into a	ccount in addition to	
	the lateral accelerations on the coil pack during railway transport.				
Date	Status	Comments			
11.4.2018	Partly imple-	Preliminary ca	alculations have been made	e, calculations are be-	
	mented	ing checked.			
25.3.2019	Partly imple-	Calculations f	or defining sufficient strap	ping of steel rolls are	
	mented	ready, but ma	aximum acceleration forces	s used in calculations	
		need to be ch	ecked.		

Date and time (Code):	8.7.2016 (R2016-0	3)		
Location:	Finland	Finland		
Type of occurrence:	Train collision	Train collision		
Train type and number:	Shunting unit, Dr14	Shunting unit, Dr14 diesel locomotive and 20 tank wagons		
Road vehicle:	-			
		In the train	In the road vehicle	
Persons on board:	Crew:	2	-	
	Passengers:	0	-	
Fatally injured:	Crew:	0	-	
	Passengers:	0	-	
Seriously injured:	Crew:	0	-	
	Passengers:	0	-	

Slightly injured:		rew:	0	-	
		Passengers: 0 -			
Damages of rolling	g stock: T	Two wagons were damaged.			
Damages on track	equipment: B	uffer stop damage	ed.		
Other damages:	F	ew.			
Disturbances of traffic:		None.			
Summary: A radio	-controlled shunti	ng unit collided w	ith a rail barrier and two tar	k wagons loaded with	
SPB gasoline were	derailed at the p	ort of Mussalo in	Kotka on the night of Frida	ay 8 July 2016. As the	
first wagon was de	railed, the end o	the second wag	on mounted the under-fram	me of the first wagon.	
Because the height	difference was s	o great, the over	ride protection on the centr	al buffer coupling was	
unable to prevent th	ne couplings from	detaching from e	each other.		
Final report issued	d: 10.3.2017				
Recommendation	The lengths of r	ailway yard tracks	s vary depending on the da	ta source and system.	
Nr. 2017-S7	During shunting	work, this can le	ad to errors of interpretatio	n which can cause an	
	incident or accid	ent. The consequ	iences of an accident can b	e significant in railway	
	yards were dang	erous goods are	being transported. To imp	rove the safety of rail-	
	way yards, the	arety investigation	on Authority recommends th	at:	
	Intrastructure	nanagers are re	esponsible for ensuring t	nat the usable track	
Data	Status	y yards are con	sistent regardless of the s	system.	
11 / 2018	Dartly imple-	Some infrastr	ucture managers have imp	lemented Information	
11.4.2010	raily inpie-	is missing from	n some infrastructure man		
25 3 2019		Most Infrastri	icture managers have en	sured that lengths of	
20.0.2010		tracks are sim	ilar in different systems	Surca that lengths of	
Recommendation	A rescue plan fo	ms the basis of s	afety in ports and other area	as where several com-	
Nr 2017-S8	nanies are oper	ting. The promot	ion of overall safety in such	an area requires con-	
	sistent actions from all operators. The ensure consistent actions, the Safety Inves-			ons, the Safety Inves-	
	tigation Authority	tigation Authority recommends that:			
	Railway undertakings should comply with local emergency plans in ports and				
	other areas wh	ere other compa	nies are also operating.		
Date	Status	Comments			
11.4.2018	Partly imple-	To be discuss	ed in infrastructure manage	rs co-operation group.	
	mented				
25.3.2019	Partly imple-	Local operato	ors and infrastructure man	agers have reviewed	
	mented	rescue plans.	Updating of rescue plans	for dangerous goods	
-		railway yards	is ongoing.	<u> </u>	
Recommendation	In railway yards,	old buffer stops	are of little relevance in stop	ping wagons. In addi-	
Nr. 2017-59	tion, the transpo	rt of dangerous g	joods in wagons built accor	ding to varying stand-	
	ards sets a wide	range of requirer	nents for buffer stops. In ris	c analyses, overshoot-	
	ngs nave been i	upting cuponvisio		lont provention should	
	he made more	affective particula	arly in railway yards where	dangerous goods are	
	being handled	To improve the s	afety of railway yards in where	hich dangerous goods are	
	are being transp	orted, the Safety	Investigation Authority reco	mmends that:	
	Infrastructure managers should modernise buffer stops on tracks whe			ps on tracks where	
	shunting work	is done related t	o the transport of danger	ous goods.	
Date	Status	Comments	· · · · · · · · · · · · · · · · · · ·		
11.4.2018	Partly imple-	Some infrastr	ucture managers have stu	died the situation and	
	mented	made action	plan for replacement. Inforr	nation is missing from	
		some infrastru	ucture managers.	-	
25.3.2019	Partly imple-	Finnish transp	oort agency has checked all	end buffers on its net-	
	mented	work and mad	de a schedule for renewal of	of obsolete buffers. In-	
		formation from	n some of the smaller infra	structure managers is	
		missing.			

Date and time (Code):	27.7.2016 (R2016-04)
Location:	Finland
Type of occurrence:	Train collision
Train type and number:	Metro trains
Road vehicle:	-

				In the train	In the road vehicle
Persons on board	:	Crev	N:	1	-
		Passengers:		0	-
Fatally injured:		Crev	N:	0	-
		Pass	sengers:	0	-
Seriously injured:		Crev	<i>v:</i>	0	-
		Pass	sengers:	0	-
Slightly injured:		Crev	v:	0	-
		Pass	sengers:	0	-
Damages of rolling	g stock:				<u> </u>
Damages on track	equipment:				
Other damages:					
Disturbances of tr	affic:				
Summary: Two me	etro trains collid	ded at	t Itäkeskus met	ro station in. The sides of t	he departing test drive
train and the teaching	ng train standi	ing at	the turnout ar	ea of the station collided a	and the test drive train
was derailed.	0	0			
Final report issued	d: 8.5.2017				
Recommendation	The accident	inves	tigation reveal	ed that the safety device c	lesign included a fault
Nr. 2017-S22	that has been	carrie	ed across two	generations of devices.	
	Helsinki Citv	Tran	sport and the	safety device supplier sh	ould investigate and
	analyse the	reaui	rements relati	ng to the operational saf	etv of the metro rail-
	way system t	horo	ughly in order	to avoid potential faults	being carried across
	to the next s	ysten	n in the course	e of the current safety de	vice revision.
Date	Status		Comments		
11.4.2018	Partly imple-		Helsinki City T	ransport (HKL) has started	to use notified bodies
	mented		to improve sa	fety devices design and in	nstallation. Safety de-
			vices will be u	nified.	
25.3.2019	Partly imple-		Definitions ha	we been analysed and c	larified during recent
	mented		safety devices	s update project. Work cont	tinues due to deficien-
	cies found in old docum		d documentation.		
Recommendation	Helsinki City Transport was not required to have a safety management system until				
Nr. 2017-S23	the summer of 2016, following the entry into force of the new Urban Rail Transport				
	Act. This is why the system was undeveloped. For example, there were shortcom-				
	ings in the processing of safety deviations, and the risk of metro trains colliding ha			tro trains colliding had	
	not been iden	tified.			
	The Finnish	Trar	nsport Safety	Agency should ensure	e that Helsinki City
	Transport's	safety	/ managemen	t system is developed so	that it meets the re-
	quirements s	set by	y the Europea	an Railway Agency (ERA)) for safety manage-
	ment system	S.			
Date	Status		Comments		
11.4.2018	Partly imple-		Finnish Trans	port Safety Agency and H	lelsinki City Transport
	mented		(HKL) have to	gether improved safety m	anagement system of
			Helsinki City I	ransport.	
25.3.2019	IMPLEMENT	ED	According to	new Rail transport legislati	ion Traficom monitors
			also Helsinki (City Transport's safety mar	agement system. Re-
			quirements in	legislation are similar to crit	eria used by European
			rallway agenc	<u>y (ERA).</u>	
Recommendation	Controlling nig	ght-tin	ne traffic is cha	allenging. Unscheduled nigh	nt-time test and teach-
Nr. 2017-524	ing traffic hac	i not i	been planned	sufficiently well or coordina	ated. It was difficult to
	form a compre	ehens	ive picture of th	ne traffic situation. Night-tim	e traffic requires traffic
	controllers to make quick decisions based on events.		the the last and a the set		
	Heisinki City	Irar	nsport snould	schedule night-time me	tro trains and other
Dete	Units and dra	aw up	a driving pro	gramme for them.	
	Dorth increte			om for doublemes and in marti	topopoo plonete e er d
11.4.2018	Party imple-			iona lor development in mair	menance planning and
25.2.2010	Dorthy imple		Holoioki City T	IUIIS.	propining of track work
23.3.2019	montod			traffic on metro lines Ale	nonising of track work
	mented		and night time	e itallic on metro lines. Als	U UI The teaching driv-
			room for impr	n up more detailed plans.	
	1			overneni in these processes	o.

Date and time (Co	de):	13.8.2916 (R2016-06)		
Location:		Finland		
Type of occurrence:		Train collision		
Train type and number:		Freight train 5316,	2 x Sr1 electric locomotives	s and 24 wagons
Road vehicle:		-		
			In the train	In the road vehicle
Persons on board	:	Crew:	1	-
		Passengers:	0	-
Fatally injured:		Crew:	0	-
		Passengers:	0	-
Seriously injured		Crew:	0	
		Passengers:	0	
Slightly injured		Crew:	1	
		Passengers:	0	
Damages of rolling	a stock	Locomotive and the	ree wagons damaged badly	Seven wagons
Damages of roming	<i>y</i> 3100 <i>K</i> .	damaged less seve	arely	. Ocveri wagons
		Track damaged ab	out 100 meters and the por	tal suspension of
Damages on track	equipment:	electric railway dan	naged	
Other damages		None		
Disturbances of tr	affic	Poilwov vord troffic	disrupted due to a power of	
				Juidye.
Summary: An emp	oty timber train	on its way from Ke	mi to Kontiomaki was abou	It to arrive at the Oulu
freight yard, where i	it was intended	to stop for two nou	rs and change drivers. The	freight train arrived on
track 118 and collid	ed with the em	pty wagons standing	g on the tracks at a speed o	<u>of 33 km/n.</u>
Final report issued	23.5.2017			
Recommendation	A safety risk i	s involved in the wo	rk done by switchmen to pr	otect routes in railway
Nr. 2017-S28	yards without	modern technical sy	stems to protect the passage	je of trains. Route pro-
	tection by the	switchman is not v	rerified in any way, which a	also constitutes a risk.
	The faulty pro	cedure used by the switchman made it possible to protect the route		
	of a train on a	n occupied track. I	raffic implemented as shun	ang operations should
	be more cont	rolled, in which case the engine driver would also have an obligation		
	to keep a look	Cout. If, say, for financial reasons it is not possible to equip all railway		
	yards with tec	nnical monitoring by	centralised traffic control, tr	he Safety Investigation
	The Finnish		abould restrict trains ru	nning on trooks that
	are not unde	r technical centralised traffic control		
Dete	Status			
	Status		and where a next of trains	routo io run occordino
11.4.2018	Under implem	en- A test is in pro	ocess where a part of trains	route is run according
	lation		will be based on it	be made from this test
25.2.2010	Dorthy impole		will be based on It.	we have abarred for
25.3.2019	Partiy Imple-		intendation, procedures ha	different presedures
Decembers			uiu raiiway yaru, partiy With	amereni procedures.
		ns on traffic control	are not consistent in all p	ans, and some of the
Nr. 2017-529	actors do not	KNOW WHICH INSTRUCT	ions should be applied to w	nich function or which
	Instructions si			er to other instructions
	that have alle	ady been repealed.	. To ensure that the instruct	tions on trainc control
	are up to uat		actors, the Safety Investiga	ation Authonity recom-
The Finnish		The man and American and a low for the function of		
		d traffic control	Should harmonise and Cla	army the instructions
Data	Status			
	Status Dorthy imple	Poilwov vord	troffic control instructions	and train traffic control
11.4.2018	Partiy Imple-	kallway yard	trainc control instructions a	and train traffic control
25.2.2010			ave been combined to a SIN	gie document.
20.3.2019		Separate Insti	uctions have been replaced	a by Traffic controller's
		manual.		

Date and time (Code):	28.6.2017 (R2017-01)
Location:	Ylivieska, Seinäjoki Ylivieska section of line, (line number 412), km
	629+164.

Annex 1/24 (28)

Type of occurrenc	e:	Incident – A track tamping machine began moving by itself – Haz-		
Train type and number		A track tamping machine		
Road vehicle	nber.	-		
			In the train	In the road vehicle
Persons on board	:	Crew:	0	-
	-	Passengers:	0	-
Fatally injured:		Crew:	0	-
		Passengers:	0	-
Seriously injured:		Crew:	0	-
		Passengers:	0	-
Slightly injured:		Crew:	0	-
		Passengers:	0	-
Damages of rolling	g stock:	None.		
Damages on track	equipment:	Point machine was	damaged.	
Other damages:		None.		
Disturbances of tr	affic:	The traffic was at a	standstill for two hours.	
Summary: A self-p	owered track m	aintenance machin	e used for track tamping be	gan moving of its own
accord from the we	stern double-tra	ack work site locate	d to the south of Ylivieska.	The machine trailed a
turnout leading from	n the work site	to a track section u	sed by traffic and rolled no	rth on a track used by
traffic for a distance	of one kilometi	re, coming to a halt	on track 1 of the Ylivieska	station. Only moments
before, the track see	ction had been	used by a freight tra	ain neading south. Passeng	er trains were on their
Final report issue		Sun South and Horth	•	
Pinal report issued	1. 14.2.2010	repenent Agency di	id not require the contract	re participating in the
	trock project to	hansport Agency u	id not require the contracto	instead it required the
NI. 2010-31	application of	the Finnish Trans	port Agency's safety man	anoment system The
	adoption of the	e system on a work	site with several contracto	rs and subcontractors
	was deficient.	as was the monitor	ing of the adoption process	
	Already at the	ne competitive te	endering phase for the	project. the Finnish
	Transport Agency should require each main contractor participating in track			
	projects to have its own safety management system that takes the special			
	characteristics of the companies and work sites into consideration and in-			
	clude monitoring of the realisation of these systems as part of its auditing			
	process.			
Date	Status	Comments		
25.3.2019	Partly imple-	Finnish transp	port agency will include sub	contractor safety man-
	mented	agement syst	em requirements to its ow	n safety management
		system. Chan	ges will be introduced durin	ng 2019.
Recommendation	The instruction	is currently in use of	to not pay attention to the s	standing locations and
Nr. 2018-52	the related pro	cedures for rolling s	stock. In this respect, the mi	ssing instructions give
	the operators	nee nanus in when	e and now to leave folling	Slock standing, which
	in the case of	maintenance mad	bines as their movements	and locations are not
	known by the	centralised traffic co	ontrol	
	The Finnish 1	ransport Agency	should add instructions t	to the safety instruc-
	tions of trac	k maintenance (T	URO) and the rail traffic	and shunting work
	safety rules (Jt) on the location	s where rolling stock may	be left standing and
	the required	procedures to sec	ure it in place.	-
Date	Status	Comments		
25.3.2019	Under implem	en- Instructions fo	or temporary storage and sta	anding places of rolling
	tation	stock and how	w to secure rolling stock in	place will be updated
		during 2019.		
Recommendation	In the worst c	ase, the inability of	the centralised traffic cont	rol to see turnouts in-
Nr. 2018-S3	stalled in a tra	ck section used by	traffic and their incomplete	connection to the rail-
	way safety sy	stem could have ca	aused a serious accident if	the maintenance ma-
	chine had stop	ped in the turnout s	ection. Furthermore, the ina	bility of the centralised
	traffic control to	o see the turnouts c	aused a significant slow-dov	wn to the post-incident
	TRACK INSPECTIO	n operations.	abaula unalata D-ut 0.0	ofatu daviana at il
	I NE FINNISh	ransport Agency	snould update Part 6, S	arety devices, of the
	∣ Kanway Engl	neering Gulaeline	S (RAID) SO that the Seci	lion of a turnout that

	acco troffic instal	lad on a treak agotion used by traffic must always be son		
	sees traine installed on a track section used by traine must always be con-			
	connected to the controlised traffic control monitoring immediately when			
	tochnically possible			
Dete				
Date	Status	Comments		
25.3.2019	IMPLEMENTED	Finnish transport agency's operating policy is that turnouts are		
		connected to safety system as soon as it is technically possible.		
		Decisions have to be made case by case when planning work		
		phases and designing safety devices. Connection of turnouts to		
		safety devices will also be included in safety plans for projects.		
Recommendation	At the time the inc	ident occurred, the brake system of the maintenance machine		
Nr. 2018-S4	was worn and poorl	y adjusted. This was the case despite a Finnish Transport Safety		
	Agency (Trafi) traff	ic worthiness and safety inspection that had been conducted on		
	the machine before	e it was taken into use. At the request of Trafi, extensive tests		
	and measurements were performed on the machine, analysing the characteristics			
	of the machine type, despite the fact that the machine type has been used in Finland			
	for over 20 years. The purpose of these tests remains unclear, as the visibly poor			
	condition of the individual machine was not detected. One factor could have been			
	the missing of the machine's maintenance documentation. The role of the party that			
	conducted these in	spections was unclear in the investigated incident, as the com-		
	pany also participa	ted in the refurbishment of the machine.		
	The Finnish Trans	port Safety Agency should specify in more detail the checks		
	required during a	traffic worthiness inspection as well as the qualification and		
	independence crit	teria for the party conducting the inspection.		
Date	Status	Comments		
25.3.2019	Under implemen-	Finnish Transport Safety Agency will describe rolling stock track		
	tation	worthiness requirements more precisely in its internal work in-		
		structions.		

Date and time (Code):	21.9.2017 (R2017	-02)	
Location:	Kouvola marshallin 193+568.	ng yard, track number 843, (line number 412), km
Type of occurrence:	Collision – A shunting locomotive with 6 wagons collided into 48 wagons loaded with timber.		
Train type and number:	Shunting unit 6403, a Dr14 diesel-hydraulic locomotive and 6 wag- ons.		
Road vehicle:	-		
		In the train	In the road vehicle
Persons on board:	Crew:	2	-
	Passengers:	0	-
Fatally injured:	Crew:	0	-
	Passengers:	0	-
Seriously injured:	Crew:	0	-
	Passengers:	0	-
Slightly injured:	Crew:	1	-
	Passengers:	0	-
Damages of rolling stock:	1 hopper wagon was seriously damaged, 2 container wagons were slightly damaged. A 20-foot tank container that was loaded on con- tainer wagon was seriously damaged.		
Damages on track equipment:	None.		
Other damages:	11 000 litres of hydrogen peroxide-water mixture leaked to ground, 10 000 litres were salvaged but had to be sent to chemical waste plant for disposal.		
Disturbances of traffic:	The traffic on track east of Kouvola was stopped for 15 minutes. Kou- vola rail yard was partly out of use for 24 hours.		
Summary: A shunting unit consisting of diesel locomotives, four empty hopper wagons and two tainer wagons loaded with tank containers containing hydrogen peroxide, on a container car co			wagons and two con- container car collided
with timber wagons standing in the eastern up yard at Kouvola.			
Final report issued: 1.6.2018			

Annex 1/26 (28)

Recommendation	Work guidance forms a major part of the training of shunting foremen. Trainee com-		
Nr. 2018-S14	petencies are not	sufficiently ensured, because the monitoring of work guidance	
	does not give a tru	e picture of the competencies of trainees. Nor does this ensure	
	that all issues have	been learned.	
	When approving s	safety management systems and persons who are respon-	
	sible for the veri	fication of personnel skills, the Finnish Transport Safety	
	Agency makes su	ire that their skills verification methods are sufficient, and	
	skills verification	is reported accordingly.	
Date	Status	Comments	
25.3.2019	Under implemen-	According to Finnish Transport Safety Agency, they use EU-	
	tation	level criteria when auditing safety management systems. Pro-	
		cedures have not been changed due to recommendation. In-	
		vestigation showed that procedures are not sufficient to ensure	
		competencies of trainees.	
Recommendation	Training at the edu	cational institute does not include the possibility to practice the	
Nr 2018-S15	use of radio-contro	led equipment. Guided training on a simulator would improve	
NI: 2010 010	the preparedness c	if trainees for work	
	Training institutio	ons in the railway sector include simulator training in the	
	training modified	ne for shunting foremen	
Date	Status	Commonts	
25 3 2019	Under implemen-	KRAO is researching on acquiring a simulator for radio-con-	
20.0.2010	tation	trolled locomotive operator training. Decision will be made dur-	
		ling 2010	
Perommendation	Track changes are	a doily activity in railway yards. If they are not done correctly and	
Nr 2018-S16	information is not n	a daily activity in failway yards. If they are not done concernly and	
NI. 2010-010	The Finnich Trans	assed onto the relevant parties, there is a might lisk of accounts.	
	in railway yarde a	port Agency under up written instructions for track changes and ansure that the operators in the vards act according to	
	III I dilway yai us a	ind ensure that the operators in the yards act according to	
Data	Ctatus	Commonte	
Dale 05.2.2010	Status Dorthy implo-	Comments	
25.5.2019	mented	pancy situation on railway yards. It should solve the issue.	
Recommendation	The radio control s	system of the locomotives responds slowly to the driver's com-	
Recommendation Nr. 2018-S17	The radio control s mands. There is no	system of the locomotives responds slowly to the driver's com- o separate emergency stop button on the radio control unit. The	
Recommendation Nr. 2018-S17	The radio control s mands. There is no delay in the radio	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical	
Recommendation Nr. 2018-S17	The radio control s mands. There is no delay in the radio situations.	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical	
Recommendation Nr. 2018-S17	The radio control s mands. There is no delay in the radio situations. The Finnish Tran	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control	
Recommendation Nr. 2018-S17	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop	
Recommendation Nr. 2018-S17	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button.	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop	
Recommendation Nr. 2018-S17 Date	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <i>Comments</i>	
Recommendation Nr. 2018-S17 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen-	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing	
Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because	
Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature.	
Recommendation Nr. 2018-S17 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in	
Recommendation Nr. 2018-S17 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions	
Recommendation Nr. 2018-S17 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified.	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio-	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti	system of the locomotives responds slowly to the driver's com- beseparate emergency stop button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio-	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settin	system of the locomotives responds slowly to the driver's com- beseparate emergency stop button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settin authorities and ther	system of the locomotives responds slowly to the driver's com- o separate emergency stop button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public re is little self-supervision.	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settir authorities and ther The Finnish Trans	system of the locomotives responds slowly to the driver's com- o separate emergency stop button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public re is little self-supervision. sport Safety Agency begin monitoring the practical imple-	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settin authorities and ther The Finnish Trans mentation of safet	system of the locomotives responds slowly to the driver's com- o separate emergency stop button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public re is little self-supervision. sport Safety Agency begin monitoring the practical imple- ty management systems.	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18 Date	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settir authorities and ther The Finnish Trans mentation of safet Status	system of the locomotives responds slowly to the driver's com- o separate emergency stop button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop <u>Comments</u> According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public re is little self-supervision. sport Safety Agency begin monitoring the practical imple- ty management systems. <u>Comments</u>	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settir authorities and ther The Finnish Trans mentation of safet Status Under implemen-	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public re is little self-supervision. sport Safety Agency begin monitoring the practical imple- ty management systems. Comments Finnish Transport and Communications Agency Traficom mon-	
Date 25.3.2019 Recommendation Nr. 2018-S17 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settir authorities and ther The Finnish Trans mentation of safet Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public te is little self-supervision. sport Safety Agency begin monitoring the practical imple- ty management systems. Comments Finnish Transport and Communications Agency Traficom mon- itors the contents of safety management systems. SIAF's im-	
Date 25.3.2019 Recommendation Nr. 2018-S17 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settir authorities and ther The Finnish Trans mentation of safet Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public te is little self-supervision. sport Safety Agency begin monitoring the practical imple- ty management systems. Comments Finnish Transport and Communications Agency Traficom mon- itors the contents of safety management systems. SIAF's im- pression is that there is needed more monitoring of practical re-	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18 Date 25.3.2019	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomotic sanctions. There is radio-controlled loc controlled work. In level of target settir authorities and ther The Finnish Trans mentation of safet Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public re is little self-supervision. Sport Safety Agency begin monitoring the practical imple- ty management systems. Comments Finnish Transport and Communications Agency Traficom mon- itors the contents of safety management systems. SIAF's im- pression is that there is needed more monitoring of practical re- alization.	
Recommendation Nr. 2018-S17 Date 25.3.2019 Recommendation Nr. 2018-S18 Date 25.3.2019 Recommendation	The radio control s mands. There is no delay in the radio situations. The Finnish Tran units used for shu button. Status Under implemen- tation Near misses and m controlled locomoti sanctions. There is radio-controlled loc controlled work. In level of target settir authorities and ther The Finnish Trans mentation of safet Status Under implemen- tation	system of the locomotives responds slowly to the driver's com- o separate <i>emergency stop</i> button on the radio control unit. The control system slows the start of emergency braking in critical sport Safety Agency (Trafi) require that the radio control unting work have a separate, non-delayed emergency stop Comments According to Trafi adding an emergency-stop button to existing rolling stock would be time consuming and expensive. Because of these reasons Trafi cannot require this kind of feature. SIAF has information, that there are radio-control systems in use in Finland that fulfil the recommendation. So, the solutions should be still clarified. inor collisions, which are not revealed, occur in the case of radio- ves. Users do not dare to report such incidents, due to fear of a no way of learning from <i>near misses</i> and collisions involving omotives, which hampers the development of the safety of radio- the railway sector, safety management systems remain at the ng, since their implementation is virtually unsupervised by public re is little self-supervision. Sport Safety Agency begin monitoring the practical imple- ty management systems. Comments Finnish Transport and Communications Agency Traficom mon- itors the contents of safety management systems. SIAF's im- pression is that there is needed more monitoring of practical re- alization.	

	accidents occur. Ho sponse Centre Adn dent site.	owever, these routes are largely unknown to the Emergency Re- ninistration, and this could hamper and delay access to the acci-	
	The Emergency Response Centre add numbered emergency service routes		
	for railway yards	to its system, and emergency duty officers be instructed to	
	locate the accider	nt site primarily through such routes.	
Date	Status	Comments	
25.3.2019	Under implemen- tation	According to Emergency response centres, emergency service routes cannot be added to its new ERICA system. Ministry of Interior has proposed that emergency service routes could be handled like normal streats so they would be visible in all road	
		maps. Finnish transport agency has checked all rail yard emer- gency service routes as a part of safety study for dangerous gods rail yards.	
Recommendation	Several railway yards have not been equipped with clearly visible track numbers at		
Nr.	the ends of tracks. Identifying the destination track can be difficult and it may come		
C10/2003R/S194	as a surprise that the track is occupied.		
	For these reasons,	the Safety Investigation Authority will open Recommendation	
	C10/2003R, intend	ed for the Finnish Transport Agency in the investigation report,	
	with the status "Not	to be implemented":	
	Railway yard trac	ks should be equipped with number plates.	
Date	Status	Comments	
25.3.2019	Partly imple- mented	Finnish transport agency is studying best possibilities to display track information to railway operators in all operating conditions. Priority is in rail yards for dangerous goods.	

Date and time (Code):		26.10.2017 (R2017-03)		
Location:		Raasepori, Skogby level crossing, line number 142, Karjaa–Hanko		
		section of line (km 183+714)		
Type of occurrence:		Level crossing accident		
Train type and number:		Passenger train 382, Dm12 rail bus		
Road vehicle:		Military off-the-road truck Sisu A2045		
			In the train	In the road vehicle
Persons on board:		Crew:	1	1
		Passengers:	15	7
Fatally injured:		Crew:	0	0
		Passengers:	1	3
Seriously injured:		Crew:	0	1
		Passengers:	0	2
Slightly injured:		Crew:	0	0
		Passengers:	0	2
Damages of rolling stock:		Front end damage to Dm12 rail bus. Military off-the-road truck was		
		wrecked totally.		
Damages on track equipment:		None.		
Other damages:		None.		
Disturbances of traffic:		Track between Tammisaari and Hanko out of service 6.5 hours.		
Summary: A rail bus travelling from		m Karjaa to Hanko collided with a Defence Forces high mobility terrain		
vehicle in Skogby, F	Raasepori, at a	n unprotected level c	crossing. A pioneer unit from	۱ the Uusimaa Brigade
was engaged in an attack exercise, moving vehicles from Skogby to Syndale			rom Skogby to Syndalen in	Hanko.
Final report issued: 7.6.2018				
Recommendation	The Defence Forces have developed their risk assessment with regard to exercises,			
Nr. 2018-S20	but this work is still in progress. The current risk assessment form does not en			form does not encour-
	age naming identified risks, but these are evaluated by predetermined risk type (e.g.			
land or sea tr		affic accidents). If the risks involved in exercises are not identified and		
	named, it is difficult to control and warn troops on exercise.			
	The Defence Forces develop the risk assessment of exercises in order to			
	identify the actual risks and name those which are identified.			
Date	Status	Comments		
25.3.2019	Partly imple-	Risk manager	ment is and has been under	[.] development in Finn-
	mented	ish defence fo	rces. Aim is to make risk ma	anagement a fixed part

		of all activities. Development program has been planned to be	
		completed by the end of year 2020.	
Recommendation	Repairs of level crossings have not always focused on the most dangerous level		
Nr. 2018-S21	crossings.		
	The Finnish Transport Agency and the Finnish Transport Safety Agency en-		
	sure that resources are allocated to improving the safety of, or removing, the		
	most dangerous level crossings.		
Date	Status	Comments	
25.3.2019	Partly imple-	Finnish transport agency is implementing the so called 65-pro-	
	mented	gram, in which safety of several level crossings will be im-	
		proved. In addition to this, the agency has introduced a new ac-	
		tion package to improve level crossing safety. Actions will be	
		realised 2018–2022.	
Recommendation	Seatbelts in the cargo space seating modules of the Defence Force's high mobility		
Nr. 2018-S22	terrain vehicles are difficult to use for soldiers in combat gear. The use of seatbelts		
	is not effectively monitored. There are guidelines on the use of seatbelts and the		
	monitoring of such use.		
	The Finnish Defence Forces develop seatbelts in cargo space seating mod-		
	ules so that they are easier to use and enhance their monitoring of the use of		
Dete	Seature Comments		
	Status	Comments	
25.3.2019	Partly imple-	Finnish defence forces is studying and planning possible tech-	
	mentea	nical changes to seatbells. Decisions on changes will be made	
		Training and manifering of east balt usage has been improved.	
Bacammandation	An operational are	a command (QAC) is not necessarily actablished along to the	
	An operational area command (OAC) is not necessarily established close to the		
NI. 2010-323	threshold for establishing such a command should be lower		
	The Ministry of the Interior ensure that an energy area command (OAO)		
	The ministry of the interior ensure that an operational area command (UAC) is set up by the public authorities in the case of long term or executional		
	is set up by the	public authorities in the case of long-term or exceptional	
	is set up by the multi-authority tag	public authorities in the case of long-term or exceptional	
Date	is set up by the multi-authority tas	public authorities in the case of long-term or exceptional sks.	
Date	is set up by the multi-authority tas Status IMPLEMENTED	public authorities in the case of long-term or exceptional sks. Comments Ministry of Interior has issued rule 1363/2018 on 1.1.2019. It	
Date 25.3.2019	is set up by the multi-authority tas <i>Status</i> IMPLEMENTED	public authorities in the case of long-term or exceptional sks. Comments Ministry of Interior has issued rule 1363/2018 on 1.1.2019. It contains orders to make plans for organising rescue services	
Date 25.3.2019	is set up by the multi-authority tas <i>Status</i> IMPLEMENTED	public authorities in the case of long-term or exceptional sks. Comments Ministry of Interior has issued rule 1363/2018 on 1.1.2019. It contains orders to make plans for organising rescue services. A part of these are command structures for demanding situa-	