



NOTE

Date 05-10-2026
Casenr. 2025-469

English translation of summary, conclusion and recommendations

Summary

On 11 October 2025 at 14:03, northbound light rail vehicle LRV125 struck a cyclist at the signal-controlled junction of Søndre Ringvej and Hovedvejen in Glostrup. The cyclist, who was travelling westbound in the southern marked cycle crossing, died shortly afterwards from injuries sustained in the collision.

Conclusion

During the site inspection conducted by the Danish Accident Investigation Board, it was established that no separate cycle signals had been installed for cyclists travelling contrary to the permitted direction of traffic.

It has not been possible for the Danish Accident Investigation Board to establish which indications informed the cyclist's decision to enter the junction.

Recommendations

The Accident Investigation Board made no recommendations following the accident.