

*The full, official version of the final report is only available in Hungarian language*

**2009-190-5**



On 8 May 2009, a regional passenger train collided with a lorry at an unprotected LC between Vásárosnamény and Nyírmada stations. As a consequence of the accident, the chief ticket inspector of the train died at the site.

*Factual statements directly connected to the occurrence of the accident*

The IC thinks that the lorry driver drove onto the LC without enough attention and caution. He had been unable to cross the LC before the train arrived, which resulted in the collision.