

YHTEENVETOTAULUKKO – DATA SUMMARY

Aika: <i>Date and time:</i>	23.3.2016, 11.53		
Paikka: <i>Location:</i>	Kokkola, Matkaneva, rataosa Seinäjoki–Ylivieska (rataosa nro 412, km 562+607) <i>Kokkola, Matkaneva, Seinäjoki–Ylivieska section of line (line number 412), km 562+607</i>		
Onnettomuustyyppi: <i>Type of accident:</i>	Törmäys esteeseen, suistuminen <i>Collision with an obstacle, derailment</i>		
Junan tyyppi ja numero: <i>Train type and number:</i>	Tavarajuna 11375 – Sr1-sähköveturi <i>Freight train 11375 – Sr1 electric locomotive</i>		
		Henkilökuntaa: <i>Crew:</i>	Matkustajia: <i>Passengers:</i>
Junassa: <i>Persons on board:</i>		1	0
Henkilövahingot: <i>Injuries:</i>	Kuollut: <i>Fatally injured:</i>	0	0
	Vakavasti loukkaantunut: <i>Seriously injured:</i>	0	0
	Lievästi loukkaantunut: <i>Slightly injured:</i>	1	0
Kalustovauriot: <i>Damages of rolling stock:</i>	Veturiin tuli vaurioita <i>Damages to the locomotive</i>		
Ratavauriot: <i>Damages on track equipment:</i>	Rataa ja ratalaitteita vaurioitui noin 250 metrin matkalta. <i>Damage to approximately 250 meters of track and track equipment.</i>		
Muut vauriot: <i>Other damages:</i>	Ei. <i>None.</i>		
Häiriöt raideliikenteelle: <i>Disturbances of traffic:</i>	Kaksiraiteisen radan toisen raiteen liikenne estyi kolme päivää. Totaalikatko kesti viisi tuntia. <i>There was an interruption of three days in rail traffic in one lane of two lane track. Totally closed for five hours.</i>		